

Cleanup Site Details

Cleanup Site ID: 60

Cleanup Site ID: 60 Facility/Site ID: 2139 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Landsburg Mine [Glossary](#)

Alternate Names: LANDSBURG MINE, LANDSBURG MINE ROGERS SEAM

LOCATION

Address: KENT KANGLEY RD & 268TH AVE SE City: RAVENSDALE Zip Code: 98051 County: King
Latitude: 47.37078 Longitude: -121.98902 WRIA: 8 Legislative District: 5 Congressional District: 8 TRS:

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Atkins, Vance Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Landsburg Mine	Upland	Cleanup Started	NW	Atkins, Vance	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	S				
Conventional Contaminants, Inorganic	C	S				
Halogenated Organics	C	S				
Metals Priority Pollutants	C	S				
Non-Halogenated Solvents	C	S				
Petroleum Products-Unspecified	C	S				
Phenolic Compounds	C	S				
Polychlorinated biPhenyls (PCB)	C	S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Initial Investigation / Federal Preliminary Assessment	Completed		12/15/1989
Interim Action	Completed	1/1/1990	12/1/1990

Cleanup Site Details

Cleanup Site ID: 60

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	7/7/1990	5/1/1991
Hazardous Sites Listing/NPL	Completed		8/15/1991
Remedial Investigation and/or Feasibility Study	Completed	7/30/1993	6/30/1997
Interim Action	Completed	6/1/2006	8/31/2008
Cleanup Action Plan	Completed	6/1/2006	7/31/2013
Order/Decree/Amendment	In Process	10/11/2013	
Order/Decree/Amendment	In Process	2/4/2021	
Non-LUST Ind Report Received	Completed		3/10/2022
Non-LUST Ind Report Received	Completed		8/24/2022
Non-LUST Ind Report Received	Completed		10/13/2022
SHARP Assessment	Completed		4/12/2024