

# Cleanup Site Details

Cleanup Site ID: 60

Cleanup Site ID: 60      Facility/Site ID: 2139      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Landsburg Mine      [Glossary](#)

Alternate Names: LANDSBURG MINE, LANDSBURG MINE ROGERS SEAM

## LOCATION

Address: KENT KANGLEY RD & 268TH AVE SE      City: RAVENSDALE      Zip Code: 98051      County: King

Latitude: 47.37078      Longitude: -121.98902      WRIA: 8      Legislative District: 5      Congressional District: 8      TRS:

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
 Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
 Site Rank: 1 - Highest Assessed Risk      NFA Reason: N/A      Brownfield? No  
 Site Manager: Atkins, Vance      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Landsburg Mine	Upland	Cleanup Started	NW	Atkins, Vance	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	S				
Conventional Contaminants, Inorganic	C	S				
Halogenated Organics	C	S				
Metals Priority Pollutants	C	S				
Non-Halogenated Solvents	C	S				
Petroleum Products-Unspecified	C	S				
Phenolic Compounds	C	S				
Polychlorinated biPhenyls (PCB)	C	S				

Key:  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Initial Investigation / Federal Preliminary Assessment	Completed		12/15/1989
Interim Action	Completed	1/1/1990	12/1/1990

# Cleanup Site Details

Cleanup Site ID: 60

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Hazard Assessment/Federal Site Inspection	Completed	7/7/1990	5/1/1991
Hazardous Sites Listing/NPL	Completed		8/15/1991
Remedial Investigation and/or Feasibility Study	Completed	7/30/1993	6/30/1997
Interim Action	Completed	6/1/2006	8/31/2008
Cleanup Action Plan	Completed	6/1/2006	7/31/2013
Order/Decree/Amendment	In Process	10/11/2013	
Order/Decree/Amendment	In Process	2/4/2021	
Non-LUST Ind Report Received	Completed		3/10/2022
Non-LUST Ind Report Received	Completed		8/24/2022
Non-LUST Ind Report Received	Completed		10/13/2022
Site Hazard Assessment/Federal Site Inspection	Completed		4/25/2024