

Cleanup Site Details

Cleanup Site ID: 6000

Cleanup Site ID: 6000 Facility/Site ID: 38465614 UST ID: 7370 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Whitty's Minimart 2 [Glossary](#)

Alternate Names: COLVILLE REDDIE LUBE INC, WHITTEN OIL EXXON, Whitty's Minimart 2, WHITTYS MINI MART 2, WHITTYS MINIMART 2

LOCATION

Address: 485 S MAIN City: COLVILLE Zip Code: 99114 County: Stevens
Latitude: 48.54047 Longitude: -117.90550 WRIA: 59 Legislative District: 7 Congressional District: 5 TRS: 35N 39E 9

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 4/21/2014 Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: Ecology Supervised/Conducted Cleanup Brownfield? No
Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WHITTY'S MINI-MART	Upland	No Further Action Required	EA	Eastern Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified			RB		RB	
Petroleum-Other	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		4/10/1990
Initial Investigation / Federal Preliminary Assessment	Completed		4/12/1990
LUST - Notification	Completed		4/12/1990
Interim Action	Completed	7/18/1990	7/18/1991
Interim Action	Completed	8/28/1990	8/28/1991
Remedial Investigation and/or Feasibility Study	Completed	3/4/1991	6/28/1991
Site Hazard Assessment/Federal Site Inspection	Completed	9/4/1991	12/3/1991
Remedial Investigation and/or Feasibility Study	Completed	10/23/1991	8/10/1993

Cleanup Site Details

Cleanup Site ID: 6000

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		2/25/1992
LUST - Site Characterization Report	Completed		8/10/1993
Interim Action	Completed	11/15/1993	12/15/1995
Cleanup Action Plan	Completed	10/10/1996	3/28/1997
Cleanup Action - Engineering Design	Completed	3/28/1997	6/9/1997
Cleanup - Construction	Completed	6/9/1997	11/1/1997
LUST - Report Received	Completed		10/31/1997
O & M	Completed	11/1/1997	6/1/2010
LUST - Report Received	Completed		5/26/1998
LUST - Report Received	Completed		3/28/2005
LUST - Report Received	Completed		10/17/2005
LUST - Report Received	Completed		5/22/2006
LUST - Report Received	Completed		10/23/2006
LUST - Report Received	Completed		4/16/2007
Periodic Review	Completed	7/1/2007	4/15/2008
LUST - Report Received	Completed		11/8/2007
LUST - Report Received	Completed		4/11/2008
LUST - Report Received	Completed		10/2/2008
LUST - Report Received	Completed		4/1/2009
LUST - Report Received	Completed		9/30/2009
LUST - Report Received	Completed		5/10/2010
LUST - Report Received	Completed		10/14/2010
LUST - Report Received	Completed		4/18/2011
LUST - Report Received	Completed		11/3/2011
LUST - Report Received	Completed		4/30/2012
LUST - Report Received	Completed		10/24/2012
LUST - Report Received	Completed		1/14/2013
LUST - Report Received	Completed		3/27/2013
LUST - Report Received	Completed		8/8/2013
LUST - Report Received	Completed		2/7/2014
Site Status Changed to NFA	Completed		4/21/2014
Remove site from Hazardous Sites List	Completed		4/21/2014
Periodic Review	In Process	12/5/2023	