

Cleanup Site Details

Cleanup Site ID: 6008

Cleanup Site ID: 6008 Facility/Site ID: 38761451 UST ID: 97377 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Lynnwood Dodge [Glossary](#)

Alternate Names: Lynnwood Dodge, Lynnwood Dodge Inc

LOCATION

Address: 20612 HWY 99 City: LYNNWOOD Zip Code: 98036 County: Snohomish
Latitude: 47.81219 Longitude: -122.32276 WRIA: 8 Legislative District: 32 Congressional District: 2 TRS: 27N 4E 20

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 2/5/2014 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Site Hazard Assessment Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
LYNNWOOD DODGE	Upland	No Further Action Required	NW	Northwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	S	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		5/8/1990
LUST - Report Received	Completed		7/23/1990
LUST - Report Received	Completed		9/27/1995
Initial Investigation / Federal Preliminary Assessment	Completed		7/1/1996
LUST - Report Received	Completed		8/12/1996
LUST - Report Received	Completed		7/30/1997
LUST - Report Received	Completed		12/23/1999
Early Notice Letter(s)	Completed		4/7/2003
VCP Opinion on Cleanup Action	Completed	4/7/2003	

Cleanup Site Details

Cleanup Site ID: 6008

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Status Request	Completed	3/31/2006	6/16/2006
Site Hazard Assessment/Federal Site Inspection	Completed	5/21/2013	9/1/2013
Site Status Changed to NFA	Completed		2/5/2014