

# Cleanup Site Details

Cleanup Site ID: 6008

Cleanup Site ID: 6008      Facility/Site ID: 38761451      UST ID: 97377      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Lynnwood Dodge      [Glossary](#)

Alternate Names: Lynnwood Dodge, Lynnwood Dodge Inc

## LOCATION

Address: 20612 HWY 99      City: LYNNWOOD      Zip Code: 98036      County: Snohomish  
Latitude: 47.81219      Longitude: -122.32276      WRIA: 8      Legislative District: 32      Congressional District: 2      TRS: 27N 4E 20

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 2/5/2014      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: Site Hazard Assessment      Brownfield? No  
Site Manager: Northwest Region      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
LYNNWOOD DODGE	Upland	No Further Action Required	NW	Northwest Region	No Process

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	S	C				
Petroleum-Other	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		5/8/1990
LUST - Report Received	Completed		7/23/1990
LUST - Report Received	Completed		9/27/1995
Initial Investigation / Federal Preliminary Assessment	Completed		7/1/1996
LUST - Report Received	Completed		8/12/1996
LUST - Report Received	Completed		7/30/1997
LUST - Report Received	Completed		12/23/1999
Early Notice Letter(s)	Completed		4/7/2003
VCP Opinion on Cleanup Action	Completed	4/7/2003	1/1/1900

# Cleanup Site Details

**Cleanup Site ID: 6008**

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Status Request	Completed	3/31/2006	6/16/2006
Site Hazard Assessment/Federal Site Inspection	Completed	5/21/2013	9/1/2013
Site Status Changed to NFA	Completed		2/5/2014