

# Cleanup Site Details

Cleanup Site ID: 6015

Cleanup Site ID: 6015      Facility/Site ID: 39196282      UST ID: 101034      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: SKS Shell Station      [Glossary](#)

Alternate Names: ALASKA ST TEXACO, Alaska Street Texaco, SKS Shell Redevelopment, SKS Shell Station, SKS Shell Station Property, Texaco

## LOCATION

Address: 3901 SW ALASKA ST      City: SEATTLE      Zip Code: 98116      County: King  
Latitude: 47.56094      Longitude: -122.38170      WRIA: 9      Legislative District: 34      Congressional District: 7      TRS: 24N 3E 23

## DETAIL

Status: Construction Complete-Performance Monitoring      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: Myers, Dale R      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SKS Shell Station	Upland	Construction Complete-Performance Monitoring	NW	Myers, Dale R	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	RB				
Lead		RB				
Metals Priority Pollutants	S					
Non-Halogenated Solvents	C					
Other Non-Halogenated Organics	C	RB				
Petroleum-Diesel	C	RB				
Petroleum-Gasoline	RA	RB				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		12/14/1998
LUST - Notification	Completed		5/17/2001
LUST - Report Received	Completed		5/17/2001

# Cleanup Site Details

Cleanup Site ID: 6015

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		6/11/2001
LUST - Report Received	Completed		1/13/2004
LUST - Report Received	Completed		1/13/2004
LUST - Report Received	Completed		1/13/2004
VCP Opinion on Cleanup Action Plan	Completed	1/13/2004	1/1/1900
LUST - Report Received	Completed		3/11/2004
VCP Status Request	Completed	3/31/2006	6/16/2006
LUST - Report Received	Completed		11/19/2008
LUST - Report Received	Completed		12/27/2008
LUST - Report Received	Completed		3/25/2009
LUST - Report Received	Completed		6/28/2009
VCP Opinion on Remedial Investigation	Canceled	10/22/2012	1/1/1900
VCP Opinion on Site Cleanup	Completed	4/19/2013	4/30/2013
Order/Decree/Amendment	Completed	7/29/2013	1/1/1900
Remedial Investigation and/or Feasibility Study	Completed		6/16/2014
Cleanup Action Plan	Completed		6/16/2016
Cleanup - Construction	Completed		10/20/2016
Cleanup - Performance Monitoring	Completed	10/26/2016	12/28/2023
LUST - Report Received	Completed		5/27/2021
LUST - Report Received	Completed		5/27/2021