

# Cleanup Site Details

Cleanup Site ID: 6015

Cleanup Site ID: 6015 Facility/Site ID: 39196282 UST ID: 101034 Site Page Site Documents View Map

Cleanup Site Name: SKS Shell Station Glossary

Alternate Names: ALASKA ST TEXACO, Alaska Street Texaco, SKS Shell Redevelopment, SKS Shell Station, SKS Shell Station Property, Texaco

LOCATION

Address: 3901 SW ALASKA ST City: SEATTLE Zip Code: 98116 County: King

Latitude: 47.56094 Longitude: -122.38170 WRIA: 9 Legislative District: 34 Congressional District: 7 TRS: 24N 3E 23

**DETAIL** 

Status: Construction Complete- NFA Received? No Is PSI site? No

Performance Monitoring

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Myers, Dale R Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SKS Shell Station	Upland	Construction Complete- Performance Monitoring	NW	Myers, Dale R	Ecology-supervised or conducted

### **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	С	RB					
Lead		RB					
Metals Priority Pollutants	S						
Non-Halogenated Solvents	С						
Other Non-Halogenated Organics	С	RB					
Petroleum-Diesel	С	RB					
Petroleum-Gasoline	RA	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		12/14/1998
LUST - Notification	Completed		5/17/2001
LUST - Report Received	Completed		5/17/2001

Toxics Cleanup Program Report Generated: 5/14/2024 Page 1 of 2



# Cleanup Site Details

ECOLOGY State of Washington	Cleanup Site Details		Cleanup Site ID: 6015			
SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Report Received	Completed		6/11/2001			
LUST - Report Received	Completed		1/13/2004			
LUST - Report Received	Completed		1/13/2004			
LUST - Report Received	Completed		1/13/2004			
VCP Opinion on Cleanup Action Plan	Completed	1/13/2004				
LUST - Report Received	Completed		3/11/2004			
VCP Status Request	Completed	3/31/2006	6/16/2006			
LUST - Report Received	Completed		11/19/2008			
LUST - Report Received	Completed		12/27/2008			
LUST - Report Received	Completed		3/25/2009			
LUST - Report Received	Completed		6/28/2009			
VCP Opinion on Remedial Investigation	Canceled	10/22/2012				
VCP Opinion on Site Cleanup	Completed	4/19/2013	4/30/2013			
Order/Decree/Amendment	Completed	7/29/2013				
Remedial Investigation and/or Feasibility Study	Completed		6/16/2014			
Cleanup Action Plan	Completed		6/16/2016			
Cleanup - Construction	Completed		10/20/2016			
Cleanup - Performance Monitoring	In Process	10/26/2016				
LUST - Report Received	Completed		5/27/2021			

Completed

LUST - Report Received

5/27/2021