

Cleanup Site Details

Cleanup Site ID: 6044 Facility/Site ID: 42128291 UST ID: 3081 Site Page Site Documents View Map

Cleanup Site ID: 6044

Cleanup Site Name: Blaine Mini Mart Glossary

Alternate Names: BLAINE MINI MART, Blaine Mini Mart - 2013

LOCATION

Address: 2530 PEACE PORTAL DR City: BLAINE Zip Code: 98230 County: Whatcom

Latitude: 48.97578 Longitude: -122.72790 WRIA: 1 Legislative District: 42 Congressional District: 1 TRS: 40N 1E 7

DETAIL

Status: Cleanup Complete-Active NFA Received? No Is PSI site? Yes

O&M/Monitoring

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Blaine Mini Mart
 Upland
 Cleanup Complete-Active O&M/Monitoring ongoing
 NW
 Northwest Region
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	С	С					
Methyl tertiary-butyl ether	С	С					
Non-Halogenated Solvents	С	С					
Petroleum-Diesel	С	С					
Petroleum-Gasoline	С	С					
Petroleum-Other	С	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above

S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
LUST - Report Received	Completed		10/30/1997
LUST - Notification	Completed		11/28/2005
Site Discovery/Release Report Received	Completed		11/28/2005

Toxics Cleanup Program Report Generated: 10/21/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
LUST - Report Received	Completed		12/9/2005		
LUST - Report Received	Completed		6/23/2008		
Cleanup Action Plan	Completed	1/1/2010	9/27/2010		
Remedial Investigation and/or Feasibility Study	Completed	4/1/2010	8/27/2010		
LUST - Site Characterization Report	Completed		7/21/2010		
Non-LUST Ind Report Received	Completed		8/27/2010		
Cleanup - Construction	Completed	4/27/2011	5/18/2011		
LUST - Report Received	Completed		8/31/2011		
Placement of Lien	Completed	3/29/2012	1/1/1900		
Cleanup - Performance Monitoring	Completed	7/1/2012	3/31/2013		
LUST - Report Received	Completed		10/12/2012		
LUST - Report Received	Completed		5/8/2013		

Cleanup Site ID: 6044