

Cleanup Site Details

Cleanup Site ID: 6057

Cleanup Site ID: 6057 Facility/Site ID: 42788675 UST ID: 2418 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Moxee POTW

[Glossary](#)

Alternate Names: CITY SHOP & WASTEWATER PLANT, MOXEE CITY SHOP & STP, MOXEE POTW, MOXEE STP

LOCATION

Address: 7520 POSTMA RD City: MOXEE Zip Code: 98936 County: Yakima
Latitude: 46.56172 Longitude: -120.40104 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 12N 19E 2

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CITY SHOP & WASTEWATER TREATMENT PLANT	Upland	Cleanup Started	CE	Central Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Lead	C	C				
Metals Priority Pollutants	C	S				
Non-Halogenated Solvents	C	C				
Petroleum-Gasoline	C	C				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/16/1993
LUST - Notification	Completed		7/18/1996
LUST - Report Received	Completed		7/18/1996
LUST - Report Received	Completed		7/16/1998
LUST - Report Received	Completed		5/25/2012

Cleanup Site Details

Cleanup Site ID: 6057

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment	Completed	2/21/2013	6/11/2013
LUST - Report Received	Completed		5/17/2013
Hazardous Sites Listing	Completed		6/11/2013
LUST - Report Received	Completed		12/18/2013
LUST - Report Received	Completed		12/18/2013
LUST - Report Received	Completed		4/7/2014
LUST - Report Received	Completed		6/16/2014
Interim Action - Plan	Completed	10/1/2014	12/5/2014
LUST - Report Received	Completed		11/7/2014
Interim Action - Construction	Completed	12/11/2014	12/12/2014
Interim Action - Performance Monitoring	Completed	1/20/2015	7/1/2017
LUST - Report Received	Completed		2/17/2015
LUST - Report Received	Completed		3/5/2015
LUST - Report Received	Completed		6/8/2015
LUST - Report Received	Completed		10/12/2015