

Cleanup Site Details

Cleanup Site ID: 6242

Cleanup Site ID: 6242 Facility/Site ID: 53876575 UST ID: 200274 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Exxon Station 73594 [Glossary](#)

Alternate Names: EXXON 7-3594, EXXON STATION 73594

LOCATION

Address: 13204 NE HWY 99 City: VANCOUVER Zip Code: 98665 County: Clark
Latitude: 45.71670 Longitude: -122.65255 WRIA: 28 Legislative District: 49 Congressional District: 3 TRS: 3N 1E 26

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 5/28/2020 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Balaraju, Panjini Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
EXXON STATION 7-3594	Upland	No Further Action Required	SW	Balaraju, Panjini	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		7/20/1988
LUST - Report Received	Completed		9/26/1988
O & M	Completed	9/26/1988	5/2/2002
LUST - Report Received	Completed		2/14/1991
LUST - Report Received	Completed		5/22/1991
LUST - Report Received	Completed		7/8/1991
LUST - Report Received	Completed		11/27/1991
LUST - Report Received	Completed		2/25/1992
LUST - Report Received	Completed		4/30/1992
LUST - Report Received	Completed		8/11/1992

Cleanup Site Details

Cleanup Site ID: 6242

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/9/1992
LUST - Report Received	Completed		3/29/1993
LUST - Report Received	Completed		6/29/1993
LUST - Report Received	Completed		4/4/1994
LUST - Report Received	Completed		4/4/1994
LUST - Report Received	Completed		9/14/1994
LUST - Report Received	Completed		6/15/1995
LUST - Report Received	Completed		12/18/1995
LUST - Report Received	Completed		4/18/1996
LUST - Report Received	Completed		6/5/1996
LUST - Report Received	Completed		12/13/1996
LUST - Report Received	Completed		11/17/1997
LUST - Report Received	Completed		4/27/1998
LUST - Report Received	Completed		3/29/1999
LUST - Report Received	Completed		4/24/2000
LUST - Report Received	Completed		1/22/2001
LUST - Report Received	Completed		7/26/2001
LUST - Report Received	Completed		12/13/2001
LUST - Report Received	Completed		5/30/2002
LUST - Report Received	Completed		9/25/2002
VCP Opinion on Cleanup Action	Completed	10/22/2002	11/16/2005
LUST - Report Received	Completed		7/2/2003
LUST - Report Received	Completed		8/7/2003
VCP Opinion on Remedial Investigation Work Plan	Completed	11/15/2006	1/16/2007
VCP Opinion on Remedial Investigation	Canceled	11/7/2007	
VCP Opinion on Remedial Investigation Work Plan	Completed	4/14/2008	6/19/2008
VCP Opinion on Remedial Investigation	Completed	9/4/2008	11/24/2008
LUST - Report Received	Completed		2/4/2010
VCP Receipt of Plan or Report	Completed		9/17/2010
LUST - Report Received	Completed		12/10/2010
LUST - Report Received	Completed		2/23/2011
LUST - Report Received	Completed		6/27/2011
VCP Opinion on Site Cleanup	Completed	8/29/2011	
LUST - Report Received	Completed		10/10/2011
VCP Receipt of Plan or Report	Completed		11/6/2012

Cleanup Site Details

Cleanup Site ID: 6242

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Site Cleanup Plan	Completed	11/6/2012	
VCP Opinion on Site Cleanup	Completed	5/16/2013	8/20/2013
Site Status Changed to NFA	Completed		8/20/2013
LUST - NFA Determination II or SHA	Completed		8/20/2013
Periodic Review	Completed	1/1/2019	3/30/2019
VCP Receipt of Plan or Report	Completed		10/7/2019
VCP Opinion on Site Cleanup	Completed	10/7/2019	5/28/2020
Reopen Site	Completed		10/14/2019
Site Status Changed to NFA	Completed		5/28/2020