

Cleanup Site Details

Cleanup Site ID: 6257

Cleanup Site ID: 6257 Facility/Site ID: 54517643 UST ID: 7633 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Yakima City Fire Department [Glossary](#)

Alternate Names: YAKIMA CITY FIRE DEPARTMENT, YAKIMA CITY FIRE DEPARTMENT UST 7633, YAKIMA FIRE DEPARTMENT

LOCATION

Address: 401 N FRONT City: YAKIMA Zip Code: 98901 County: Yakima
Latitude: 46.60727 Longitude: -120.51008 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 13N 18E 13

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 9/30/2018 Current VCP? No Past VCP? No
Site Rank: 5 - Lowest Assessed Risk NFA Reason: Ecology Supervised/Conducted Cleanup Brownfield? No
Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|------------------------|-----------|----------------------------|-----------|----------------|--------------------|
| YAKIMA FIRE DEPARTMENT | Upland | No Further Action Required | CE | Central Region | Independent Action |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Petroleum-Diesel | RB | B | | | | |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| LUST - Notification | Completed | | 11/18/1997 |
| LUST - Report Received | Completed | | 1/9/1998 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 9/28/1998 |
| Early Notice Letter(s) | Completed | | 2/28/2000 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 4/4/2000 | 7/14/2000 |
| Hazardous Sites Listing/NPL | Completed | | 7/14/2000 |
| LUST - Report Received | Completed | | 2/8/2017 |
| Petroleum Contaminated Soil Model Remedies | Completed | | 4/10/2017 |
| Remove site from Hazardous Sites List | Completed | | 9/30/2018 |

Cleanup Site Details

Cleanup Site ID: 6257

| SITE ACTIVITIES | | | |
|----------------------------|-----------|------------|------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Site Status Changed to NFA | Completed | | 9/30/2018 |