

Cleanup Site Details

Cleanup Site ID: 6257
Cleanup Site ID: 6257 **Facility/Site ID:** 54517643 **UST ID:** 7633 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Yakima City Fire Department [Glossary](#)
Alternate Names: YAKIMA CITY FIRE DEPARTMENT, YAKIMA CITY FIRE DEPARTMENT UST 7633, YAKIMA FIRE DEPARTMENT

LOCATION
Address: 401 N FRONT **City:** YAKIMA **Zip Code:** 98901 **County:** Yakima
Latitude: 46.60727 **Longitude:** -120.51008 **WRIA:** 37 **Legislative District:** 15 **Congressional District:** 4 **TRS:** 13N 18E 13

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 9/30/2018	Current VCP? No Past VCP? No
Site Rank: 5 - Lowest Assessed Risk	NFA Reason: Ecology Supervised/Conducted Cleanup	Brownfield? No
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
YAKIMA FIRE DEPARTMENT	Upland	No Further Action Required	CE	Central Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB	B				

Key:

B - Below Cleanup Level	C - Confirmed Above Cleanup Level	RA - Remediated-Above
S - Suspected	R - Remediated	RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		11/18/1997
LUST - Report Received	Completed		1/9/1998
Initial Investigation / Federal Preliminary Assessment	Completed		9/28/1998
Early Notice Letter(s)	Completed		2/28/2000
Site Hazard Assessment/Federal Site Inspection	Completed	4/4/2000	7/14/2000
Hazardous Sites Listing/NPL	Completed		7/14/2000
LUST - Report Received	Completed		2/8/2017
Petroleum Contaminated Soil Model Remedies	Completed		4/10/2017
Remove site from Hazardous Sites List	Completed		9/30/2018

Cleanup Site Details

Cleanup Site ID: 6257

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Status Changed to NFA	Completed		9/30/2018