		Cleanup	Site [Deta	ails		C	Cleanup	Site ID: 626
Cleanup Site ID: 6265 Fa	acility/Site ID:	54832356	UST ID: 509	011		Site Pag	e <u>Site Do</u>	ocuments	View Map
Cleanup Site Name: ARCO SERV	/ICE STATION (855							<u>Glossary</u>
Alternate Names: ARCO SERVIC WAKEFIELD	E STATION 085	5, ARCO SERVICI	E STATION 0	855 FO	RMER, F	ORMER	ARCO SER\	/ICE STAT	TION 0855, RD
LOCATION									
Address: 4603 OCEAN BEACH H	IWY	(City: LONGV	IEW	Zip	Code: 98	632 Co	ounty: Co	wlitz
Latitude: 46.16393 Longitude	: -123.00081	WRIA: 25 L	egislative D	strict:	19 (congressi	onal Distric	t: 3 TF	RS: 8N 3W 24
DETAIL									
Status: No Further Action	: No Further Action NFA Received? Yes Is PSI site?						No		
Statute: MTCA	Date: 4/	4/14/2015 Current VCP?						ast VCP? Yes	
Site Rank: N/A	NFA	Reason: Ve	oluntary Clear	nup Prog	gram Rev	view Bro	wnfield?	No	
Site Manager: Middleton, Tom	Resp	onsible Unit: So	outhwest			Ac	ive Instituti	onal Cont	rol? No
CLEANUP UNITS									
Cleanup Unit Name	Unit Type	Unit Sta	tus	Resp Unit	Uni	t Manage		Current Process	
ARCO #855 - WAKEFIELD PROPERTY	Upland	No Further Actio	n Required	SW	Mido	Middleton, Tom		Standard Voluntary Cleanup Program	
ACTIVE INSTITUTIONAL CONTRO	DLS								
Instrument Type Restriction Media	Rest	rictions/Requiren	Requirements		Date Recor			cording County	Tax Parcel
AFFECTED MEDIA & CONTAMINA	ANTS								
Contaminant						MEDI	٨		
		Soil	Ground	water	Surfac	MEDI e Water	A Sediment	Air	Bedrock
Metals Priority Pollutants		Soil B	Ground	water	Surfac			Air	Bedrock
-			Ground		Surfac			Air	Bedrock
Non-Halogenated Solvents		В			Surfac			Air	Bedrock
Metals Priority Pollutants Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons		B RB	RE		Surfac			Air	Bedrock
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: B - Below Cleanup Level C -	Confirmed Abov Remediated	B RB RB	RE	ediated	-Above			Air	Bedrock
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: B - Below Cleanup Level C - S - Suspected R -		B RB RB RB	RA - Rem	ediated	-Above			Air	Bedrock
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: B - Below Cleanup Level C - S - Suspected R - SITE ACTIVITIES		B RB RB RB	RA - Rem	ediated	-Above				End Date/
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: 3 - Below Cleanup Level C - 5 - Suspected R - SITE ACTIVITIES Activity	Remediated	B RB RB RB	RA - Rem	ediated	-Above -Below	e Water	Sediment		End Date/
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: 3 - Below Cleanup Level C - 5 - Suspected R - SITE ACTIVITIES Activity Site Discovery/Release Report Reco	Remediated	B RB RB RB	RA - Rem	ediated- ediated-	Above Below Status	e Water	Sediment		End Date/ ompletion Date
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: 3 - Below Cleanup Level C - S - Suspected R - SITE ACTIVITIES Activity Site Discovery/Release Report Reco	Remediated	B RB RB RB	RA - Rem	ediated ediated	-Above Below Status Complete	e Water	Sediment		End Date/ ompletion Date 8/3/1999
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: B - Below Cleanup Level C - S - Suspected R - SITE ACTIVITIES Activity Site Discovery/Release Report Rece LUST - Notification LUST - Report Received	Remediated	B RB RB RB	RA - Rem	ediated ediated ediated C C C	Above Below Status Complete	e Water	Sediment		End Date/ ompletion Date 8/3/1999 10/18/1999
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: B - Below Cleanup Level C - S - Suspected R - SITE ACTIVITIES Activity Site Discovery/Release Report Received LUST - Notification LUST - Report Received LUST - Report Received	Remediated	B RB RB RB	RA - Rem	ediated ediated ediated cC CC	Above Below Status Complete Complete	e Water d d d d d	Sediment		End Date/ ompletion Date 8/3/1999 10/18/1999 10/19/1999
Non-Halogenated Solvents Petroleum-Other Polycyclic Aromatic Hydrocarbons Key: B - Below Cleanup Level C -	Remediated	B RB RB RB	RA - Rem	ediated ediated diated CC CC	Above Below Status Complete Complete	e Water	Sediment		End Date/ ompletion Date 8/3/1999 10/18/1999 10/19/1999 6/7/2000



Cleanup Site Details

Activity	Status	Start Date	End Date/ Completion Date
LUST - Site Characterization Report	Completed		6/27/2001
LUST - Report Received	Completed		9/24/2001
LUST - Report Received	Completed		1/7/2002
LUST - Report Received	Completed		2/21/2002
LUST - Report Received	Completed		6/18/2004
LUST - Report Received	Completed		2/17/2005
LUST - Report Received	Completed		9/14/2005
VCP Opinion on Remedial Investigation	Completed	7/12/2007	10/11/2007
VCP Opinion on Interim Action Work Plan	Completed	8/15/2007	8/21/2007
VCP Opinion on Feasibility Study	Completed	1/11/2008	4/10/2008
VCP Receipt of Plan or Report	Completed		7/23/2010
LUST - Report Received	Completed		10/27/2010
LUST - Report Received	Completed		1/6/2011
LUST - Report Received	Completed		1/19/2011
LUST - Report Received	Completed		5/24/2011
LUST - Report Received	Completed		7/22/2011
LUST - Report Received	Completed		11/2/2011
LUST - Report Received	Completed		1/11/2012
LUST - Report Received	Completed		2/14/2012
LUST - Report Received	Completed		4/16/2012
LUST - Report Received	Completed		8/13/2012
LUST - Report Received	Completed		11/28/2012
LUST - Report Received	Completed		2/28/2013
LUST - Report Received	Completed		1/24/2014
LUST - Report Received	Completed		4/21/2014
LUST - Report Received	Completed		8/22/2014
LUST - Report Received	Completed		10/21/2014
VCP Opinion on Site Cleanup	Completed	10/21/2014	4/14/2015
Site Status Changed to NFA	Completed		4/14/2015