

Cleanup Site ID: 628

## Cleanup Site Details

Facility/Site ID: 10587741 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 628

Cleanup Site Name: TC Systems Inc

Alternate Names: TC SYSTEMS INC, Tri Coatings

LOCATION

Address: 1032 W MARINE VIEW DR City: EVERETT Zip Code: 98201 County: Snohomish

Latitude: 48.00371 Longitude: -122.21518 WRIA: 7 Legislative District: 38 Congressional District: 2 TRS: 29N 5E 18

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Reed, Kristen Responsible Unit: Headquarters Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TC SYSTEMS INC	Upland	Cleanup Started	HQ	Reed, Kristen	Ecology-supervised or conducted

## **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Arsenic	С	С						
Base/Neutral/Acid Organics		S						
Lead	С							
Metals Priority Pollutants	С	С						
Non-Halogenated Solvents		S						
Other Halogenated Organics	С							
Petroleum Products-Unspecified		С						
Petroleum-Diesel	S							
Petroleum-Gasoline	С							
Phenolic Compounds	С							
Polychlorinated biPhenyls (PCB)	С	S						
Polycyclic Aromatic Hydrocarbons	С	S						

Key:

B - Below Cleanup Level S - Suspected C - Confirmed Above Cleanup Level R - Remediated RA - Remediated-Above

RB - Remediated-Below

Toxics Cleanup Program Report Generated: 4/25/2024 Page 1 of 2



Interim Action - Construction

## Cleanup Site Details

SITE ACTIVITIES							
Activity	Status	Start Date	End Date/ Completion Date				
Initial Investigation / Federal Preliminary Assessment	Completed		9/1/2009				
Initial Investigation / Federal Preliminary Assessment	Completed		9/1/2009				
Early Notice Letter(s)	Completed		11/20/2009				
Order/Decree/Amendment	In Process	3/1/2010					
Remedial Investigation and/or Feasibility Study	In Process	4/25/2011					
Site Hazard Assessment/Federal Site Inspection	Completed	8/29/2013	1/16/2015				
Remedial Investigation and/or FS Work Plan	Completed	1/15/2014	3/5/2014				
Non-LUST Ind Report Received	Completed		7/30/2014				
Hazardous Sites Listing/NPL	Completed		2/5/2015				
Non-LUST Ind Report Received	Completed		10/30/2015				

Completed

4/29/2019

Cleanup Site ID: 628

5/31/2019