

# Cleanup Site Details

Cleanup Site ID: 628

**Cleanup Site ID:** 628     
**Facility/Site ID:** 10587741     
**UST ID:** N/A     
[Site Page](#)   
[Site Documents](#)   
[View Map](#)  
**Cleanup Site Name:** TC Systems Inc     
[Glossary](#)  
**Alternate Names:** TC SYSTEMS INC, Tri Coatings

## LOCATION

**Address:** 1032 W MARINE VIEW DR     
**City:** EVERETT     
**Zip Code:** 98201     
**County:** Snohomish  
**Latitude:** 48.00371   
**Longitude:** -122.21518   
**WRIA:** 7     
**Legislative District:** 38     
**Congressional District:** 2     
**TRS:** 29N 5E 18

## DETAIL

**Status:** Cleanup Started     
**NFA Received?** No     
**Is PSI site?** Yes  
**Statute:** MTCA     
**NFA Date:** N/A     
**Current VCP?** No   
**Past VCP?** No  
**Site Rank:** 1 - Highest Assessed Risk     
**NFA Reason:** N/A     
**Brownfield?** No  
**Site Manager:** Reed, Kristen     
**Responsible Unit:** Headquarters     
**Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TC SYSTEMS INC	Upland	Cleanup Started	HQ	Reed, Kristen	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	C				
Base/Neutral/Acid Organics		S				
Lead	C					
Metals Priority Pollutants	C	C				
Non-Halogenated Solvents		S				
Other Halogenated Organics	C					
Petroleum Products-Unspecified		C				
Petroleum-Diesel	S					
Petroleum-Gasoline	C					
Phenolic Compounds	C					
Polychlorinated biPhenyls (PCB)	C	S				
Polycyclic Aromatic Hydrocarbons	C	S				

**Key:**  
B - Below Cleanup Level     
C - Confirmed Above Cleanup Level     
RA - Remediated-Above  
S - Suspected                     
R - Remediated                     
RB - Remediated-Below

# Cleanup Site Details

Cleanup Site ID: 628

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Initial Investigation / Federal Preliminary Assessment	Completed		9/1/2009
Initial Investigation / Federal Preliminary Assessment	Completed		9/1/2009
Early Notice Letter(s)	Completed		11/20/2009
Order/Decree/Amendment	In Process	3/1/2010	
Remedial Investigation and/or Feasibility Study	In Process	4/25/2011	
Site Hazard Assessment/Federal Site Inspection	Completed	8/29/2013	1/16/2015
Remedial Investigation and/or FS Work Plan	Completed	1/15/2014	3/5/2014
Non-LUST Ind Report Received	Completed		7/30/2014
Hazardous Sites Listing/NPL	Completed		2/5/2015
Non-LUST Ind Report Received	Completed		10/30/2015
Interim Action - Construction	Completed	4/29/2019	5/31/2019