

Cleanup Site Details

Cleanup Site ID: 63

Cleanup Site ID: 63 Facility/Site ID: 2888 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Blaine Marina Inc Glossary

Alternate Names: BLAINE MARINA Inc

LOCATION

Address: 214 SIGURDSON AVE City: BLAINE Zip Code: 98230 County: Whatcom

Latitude: 48.99257 Longitude: -122.76434 WRIA: 1 Legislative District: 42 Congressional District: 1 TRS: 40N 1W 1

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Johnson, Beau Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BLAINE MARINA Inc	Sediment	Awaiting Cleanup	NW	Johnson, Beau	Ecology-supervised or conducted
Blaine Marina Inc	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	ment Type Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
mstrument Type	Media	Restrictions/Requirements	Date	Number	County	I ax Faicei

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Non-Halogenated Solvents	S	S	S				
Petroleum Products-Unspecified	С	С					
Petroleum-Diesel				В			
Petroleum-Other				В			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/12/1990
Early Notice Letter(s)	Completed		7/19/1990
Site Hazard Assessment	Completed	3/1/2001	8/21/2001
Hazardous Sites Listing	Completed		8/28/2001
Non-LUST Ind Report Received	Completed		12/19/2011
Order/Decree/Amendment	In Process	12/19/2011	

Toxics Cleanup Program Report Generated: 11/14/2025 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 63

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Interim Action - Plan	Completed	1/2/2012	7/11/2012			
Remedial Investigation and/or FS Work Plan	Completed	7/23/2012	10/4/2012			
Interim Action - Construction	Completed	8/20/2012	10/16/2012			
Non-LUST Ind Report Received	Completed		10/8/2012			
Non-LUST Ind Report Received	Completed		12/10/2012			
Non-LUST Ind Report Received	Completed		12/10/2012			
Non-LUST Ind Report Received	Completed		2/26/2013			
Remedial Investigation and/or Feasibility Study	Completed	12/12/2014	8/20/2015			
Cleanup Action Plan	Completed	12/16/2015	5/5/2017			
Order/Decree/Amendment	In Process	8/2/2016				
Cleanup - Construction	Completed	8/1/2018	12/31/2018			
SHARP Assessment	Completed		2/8/2024			