

# Cleanup Site Details

Cleanup Site ID: 63

**Cleanup Site ID:** 63      **Facility/Site ID:** 2888      **UST ID:** N/A      [Site Page](#)    [Site Documents](#)    [View Map](#)  
**Cleanup Site Name:** Blaine Marina Inc      [Glossary](#)  
**Alternate Names:** BLAINE MARINA Inc

## LOCATION

**Address:** 214 SIGURDSON AVE      **City:** BLAINE      **Zip Code:** 98230      **County:** Whatcom  
**Latitude:** 48.99257    **Longitude:** -122.76434    **WRIA:** 1      **Legislative District:** 42      **Congressional District:** 1      **TRS:** 40N 1W 1

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** Yes  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No    **Past VCP?** No  
**Site Rank:** 3 - Moderate Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Johnson, Beau      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BLAINE MARINA Inc	Sediment	Awaiting Cleanup	NW	Johnson, Beau	Ecology-supervised or conducted
Blaine Marina Inc	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Non-Halogenated Solvents	S	S	S			
Petroleum Products-Unspecified	C	C				
Petroleum-Diesel				B		
Petroleum-Other				B		

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/12/1990
Early Notice Letter(s)	Completed		7/19/1990
Site Hazard Assessment/Federal Site Inspection	Completed	3/1/2001	8/21/2001
Hazardous Sites Listing/NPL	Completed		8/28/2001
Non-LUST Ind Report Received	Completed		12/19/2011
Order/Decree/Amendment	In Process	12/19/2011	

# Cleanup Site Details

Cleanup Site ID: 63

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Interim Action - Plan	Completed	1/2/2012	7/11/2012
Remedial Investigation and/or FS Work Plan	Completed	7/23/2012	10/4/2012
Interim Action - Construction	Completed	8/20/2012	10/16/2012
Non-LUST Ind Report Received	Completed		10/8/2012
Non-LUST Ind Report Received	Completed		12/10/2012
Non-LUST Ind Report Received	Completed		12/10/2012
Non-LUST Ind Report Received	Completed		2/26/2013
Remedial Investigation and/or Feasibility Study	Completed	12/12/2014	8/20/2015
Cleanup Action Plan	Completed	12/16/2015	5/5/2017
Order/Decree/Amendment	In Process	8/2/2016	
Cleanup - Construction	Completed	8/1/2018	12/31/2018
Site Hazard Assessment/Federal Site Inspection	Completed		2/8/2024