

Cleanup Site Details

Cleanup Site ID: 63

Cleanup Site ID: 63 **Facility/Site ID:** 2888 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Blaine Marina Inc [Glossary](#)
Alternate Names: BLAINE MARINA Inc

LOCATION

Address: 214 SIGURDSON AVE **City:** BLAINE **Zip Code:** 98230 **County:** Whatcom
Latitude: 48.99257 **Longitude:** -122.76434 **WRIA:** 1 **Legislative District:** 42 **Congressional District:** 1 **TRS:** 40N 1W 1

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Johnson, Beau **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BLAINE MARINA Inc	Sediment	Awaiting Cleanup	NW	Johnson, Beau	Ecology-supervised or conducted
Blaine Marina Inc	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Non-Halogenated Solvents	S	S	S			
Petroleum Products-Unspecified	C	C				
Petroleum-Diesel				B		
Petroleum-Other				B		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/12/1990
Early Notice Letter(s)	Completed		7/19/1990
Site Hazard Assessment	Completed	3/1/2001	8/21/2001
Hazardous Sites Listing	Completed		8/28/2001
Non-LUST Ind Report Received	Completed		12/19/2011
Order/Decree/Amendment	In Process	12/19/2011	

Cleanup Site Details

Cleanup Site ID: 63

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Interim Action - Plan	Completed	1/2/2012	7/11/2012
Remedial Investigation and/or FS Work Plan	Completed	7/23/2012	10/4/2012
Interim Action - Construction	Completed	8/20/2012	10/16/2012
Non-LUST Ind Report Received	Completed		10/8/2012
Non-LUST Ind Report Received	Completed		12/10/2012
Non-LUST Ind Report Received	Completed		12/10/2012
Non-LUST Ind Report Received	Completed		2/26/2013
Remedial Investigation and/or Feasibility Study	Completed	12/12/2014	8/20/2015
Cleanup Action Plan	Completed	12/16/2015	5/5/2017
Order/Decree/Amendment	In Process	8/2/2016	
Cleanup - Construction	Completed	8/1/2018	12/31/2018
SHARP Assessment	Completed		2/8/2024