

Cleanup Site Details

Cleanup Site ID: 6336

Cleanup Site ID: 6336 Facility/Site ID: 58168724 UST ID: 427 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Mr Sudsy Car Wash Kent [Glossary](#)

Alternate Names: Mr Sudsy Car Wash Kent, MR SUDSY CAR WASHES INC, MR SUDSY CARWASH INC KENT, SUPER SUDSY CAR WASH, THREE PILLARS LLC

LOCATION

Address: 209 CENTRAL AVE S City: KENT Zip Code: 98032 County: King
Latitude: 47.38038 Longitude: -122.23127 WRIA: 9 Legislative District: 33 Congressional District: 9 TRS: 22N 4E 24

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 2/28/2020 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Petroleum Technical Assistance Program (PTAP) by PLIA Brownfield? No
Site Manager: PLIA Responsible Unit: Pollution Liability Ins Agcy Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Mr Sudsy Car Wash	Upland	No Further Action Required	PLIA	PLIA	PLIA Petroleum Technical

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		7/16/1992
LUST - Report Received	Completed		8/31/1992
LUST - Report Received	Completed		10/1/1998
VCP Opinion on Cleanup Action	Canceled	9/6/2002	1/1/1900
VCP Status Request	Completed	3/31/2006	6/16/2006
VCP Opinion on Interim Action	Completed	3/18/2010	1/1/1900
LUST - Report Received	Completed		3/31/2010
LUST - Report Received	Completed		3/31/2010
LUST - Report Received	Completed		3/31/2010

Cleanup Site Details

Cleanup Site ID: 6336

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		3/31/2010
LUST - Report Received	Completed		3/31/2010
LUST - Report Received	Completed		3/31/2010
VCP Opinion on Remedial Investigation Work Plan	Completed	6/23/2010	8/2/2010
LUST - Report Received	Completed		12/26/2014
Site Status Changed to NFA	Completed		2/28/2020