

Cleanup Site Details

Cleanup Site ID: 6383

Cleanup Site ID: 6383 Facility/Site ID: 61834259 UST ID: 8382 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Unocal Bulk Plant 0046 [Glossary](#)

Alternate Names: GARWOOD OIL CO BINGEN, Unocal Bulk Plant 0046

LOCATION

Address: 217 E STEUBEN ST City: BINGEN Zip Code: 98605 County: Klickitat
Latitude: 45.71412 Longitude: -121.46499 WRIA: 29 Legislative District: 14 Congressional District: 3 TRS: 3N 11E 29

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Lind, Jennifer Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Unocal Bulk Plant 0046	Upland	Cleanup Started	CE	Lind, Jennifer	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C	C	S			
Petroleum-Other	C	C	S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		8/27/1990
LUST - Notification	Completed		8/27/1990
LUST - Report Received	Completed		8/30/1990
LUST - Report Received	Completed		2/25/1991
LUST - Report Received	Completed		7/13/1994
LUST - Report Received	Completed		10/21/1994
LUST - Report Received	Completed		2/25/2003
Site Hazard Assessment/Federal Site Inspection	Completed	10/17/2007	1/18/2008
Early Notice Letter(s)	Completed		1/2/2008

Cleanup Site Details

Cleanup Site ID: 6383

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		2/20/2008
LUST - Report Received	Completed		8/22/2018
Order/Decree/Amendment	In Process	5/16/2019	
LUST - Report Received	Completed		9/18/2019
Remedial Investigation and/or FS Work Plan	In Process	8/24/2020	
LUST - Report Received	Completed		12/4/2023