

# Cleanup Site Details

Cleanup Site ID: 6383

Cleanup Site ID: 6383      Facility/Site ID: 61834259      UST ID: 8382      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Unocal Bulk Plant 0046      [Glossary](#)

Alternate Names: GARWOOD OIL CO BINGEN, Unocal Bulk Plant 0046

## LOCATION

Address: 217 E STEUBEN ST      City: BINGEN      Zip Code: 98605      County: Klickitat  
Latitude: 45.71412      Longitude: -121.46499      WRIA: 29      Legislative District: 14      Congressional District: 3      TRS: 3N 11E 29

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? Yes  
Site Rank: 3 - Moderate Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Lind, Jennifer      Responsible Unit: Central      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Unocal Bulk Plant 0046	Upland	Cleanup Started	CE	Lind, Jennifer	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C	C	S			
Petroleum-Other	C	C	S			

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		8/27/1990
LUST - Notification	Completed		8/27/1990
LUST - Report Received	Completed		8/30/1990
LUST - Report Received	Completed		2/25/1991
LUST - Report Received	Completed		7/13/1994
LUST - Report Received	Completed		10/21/1994
LUST - Report Received	Completed		2/25/2003
Site Hazard Assessment/Federal Site Inspection	Completed	10/17/2007	1/18/2008
Early Notice Letter(s)	Completed		1/2/2008

# Cleanup Site Details

Cleanup Site ID: 6383

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing/NPL	Completed		2/20/2008
LUST - Report Received	Completed		8/22/2018
Order/Decree/Amendment	In Process	5/16/2019	
LUST - Report Received	Completed		9/18/2019
Remedial Investigation and/or FS Work Plan	In Process	8/24/2020	
LUST - Report Received	Completed		12/4/2023