

# Cleanup Site Details

Cleanup Site ID: 6383

**Cleanup Site ID:** 6383     
**Facility/Site ID:** 61834259     
**UST ID:** 8382     
[Site Page](#)   
[Site Documents](#)   
[View Map](#)  
**Cleanup Site Name:** Unocal Bulk Plant 0046     
[Glossary](#)  
**Alternate Names:** GARWOOD OIL CO BINGEN, Unocal Bulk Plant 0046

## LOCATION

**Address:** 217 E STEUBEN ST     
**City:** BINGEN     
**Zip Code:** 98605     
**County:** Klickitat  
**Latitude:** 45.71412   
**Longitude:** -121.46499   
**WRIA:** 29   
**Legislative District:** 14   
**Congressional District:** 3   
**TRS:** 3N 11E 29

## DETAIL

**Status:** Cleanup Started     
**NFA Received?** No     
**Is PSI site?** No  
**Statute:** MTCA     
**NFA Date:** N/A     
**Current VCP?** No   
**Past VCP?** Yes  
**Site Rank:** 3 - Moderate Risk     
**NFA Reason:** N/A     
**Brownfield?** No  
**Site Manager:** Lind, Jennifer     
**Responsible Unit:** Central     
**Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Unocal Bulk Plant 0046	Upland	Cleanup Started	CE	Lind, Jennifer	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C	C	S			
Petroleum-Other	C	C	S			

### Key:

B - Below Cleanup Level     
C - Confirmed Above Cleanup Level     
RA - Remediated-Above  
S - Suspected                     
R - Remediated                     
RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		8/27/1990
LUST - Notification	Completed		8/27/1990
LUST - Report Received	Completed		8/30/1990
LUST - Report Received	Completed		2/25/1991
LUST - Report Received	Completed		7/13/1994
LUST - Report Received	Completed		10/21/1994
LUST - Report Received	Completed		2/25/2003
Site Hazard Assessment/Federal Site Inspection	Completed	10/17/2007	1/18/2008
Early Notice Letter(s)	Completed		1/2/2008

# Cleanup Site Details

Cleanup Site ID: 6383

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Hazardous Sites Listing/NPL	Completed		2/20/2008
LUST - Report Received	Completed		8/22/2018
Order/Decree/Amendment	In Process	5/16/2019	
LUST - Report Received	Completed		9/18/2019
Remedial Investigation and/or FS Work Plan	In Process	8/24/2020	
LUST - Report Received	Completed		12/4/2023