Cleanup Site Details Cleanup Site ID: 6393														
Cleanup Site ID: 63	leanup Site ID: 6393 Facility/Site ID: 622713			UST ID: 7478			Site Page			Site Documents View Map				
Cleanup Site Name: Sunnyside Valley Irrigation District Granger Site Glossary														
Alternate Names: SUNNYSIDE VALLEY IRRIG DIST UST 7478, SUNNYSIDE VALLEY IRRIGATION DISTRICT, Sunnyside Valley Irrigation District Granger Site														
LOCATION														
Address: 391 Gurley Rd City: Granger								Zip Code: 98932 County: Yakima						
Latitude: 46.37563 Longitude: -120.18105 WRIA: 37 Legislative Dis							strict: 15 Congressional District: 4 TRS: 10N 21E 3							
DETAIL														
Status: No Furth	Status: No Further Action NFA Receive			ed? Yes Is PSI					SI site?	site? No				
Statute: MTCA NFA Date:			Date:	9/30/2024 Curren					ent VC	t VCP? No Past VCP? No				
					ology Supervised/Conducted Brownfield? No eanup									
Site Manager: Wisotzkey, Chelsea Responsible Unit: Central Active Institution									itutional C	ontrol?	No			
CLEANUP UNITS														
Cleanup U	nit Name	Unit Type	Unit Type Unit		us	Resp Unit Unit Ma		Manager		Current		nt Process		
Sunnyside Valley Irri Granger Site	Upland	No Fur	ther Action	n Required	CE	Wisotzkey, Chelse		ea	Independent Action					
ACTIVE INSTITUTIONAL CONTROLS														
Instrument Type	ument Type Restriction Restrictions/Requi				ents	nts Date			rding Record nber Coun					
There are no current Institutional Controls in effect for this site. AFFECTED MEDIA & CONTAMINANTS														
MEDIA & CONTAMINANTS														
Contaminant				Soil	Ground	Groundwater Surface Water S			Sedim	liment Air Bed		Bedrock		
Petroleum-Diesel				RB										
Petroleum-Gasoline				RB										
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below														
SITE ACTIVITIES														
Activity							Status		Start D	Start Date C		nd Date/ Dietion Date		
LUST Review Memo							Completed							
Site Discovery/Release Report Received							Completed			3/3/1993				
LUST - Notification							Completed			3/3/1993				
LUST - Report Received							Completed			3/3/1993				
Site Status Changed to NFA							Completed			9/30/2024				
Site Hazard Assessment/Federal Site Inspection								Completed 12			2/9/2024 3/11/2025			