

# Cleanup Site Details

Cleanup Site ID: 6528

Cleanup Site ID: 6528      Facility/Site ID: 69431927      UST ID: 5995      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Astro Western Station 607      [Glossary](#)

Alternate Names: A TRAIL MART 607, ASTRO WESTERN STATION 607

## LOCATION

Address: 13117 NE HIGHWAY 99      City: VANCOUVER      Zip Code: 98686      County: Clark

Latitude: 45.71737      Longitude: -122.65193      WRIA: 28      Legislative District: 49      Congressional District: 3      TRS:

## DETAIL

<b>Status:</b> No Further Action	<b>NFA Received?</b> Yes	<b>Is PSI site?</b> No
<b>Statute:</b> MTCA	<b>NFA Date:</b> 12/17/2009	<b>Current VCP?</b> No <b>Past VCP?</b> Yes
<b>Site Rank:</b> N/A	<b>NFA Reason:</b> Voluntary Cleanup Program Review	<b>Brownfield?</b> No
<b>Site Manager:</b> Rose, Scott	<b>Responsible Unit:</b> Southwest	<b>Active Institutional Control?</b> No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ASTRO #607	Upland	No Further Action Required	SW	Southwest Region	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants		RA				
Non-Halogenated Solvents		RA				
Petroleum-Other	RA	RA				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/28/1996
LUST - Report Received	Completed		6/7/1996
LUST - Report Received	Completed		1/13/1997
LUST - Report Received	Completed		2/14/1997
LUST - Report Received	Completed		5/9/1997
Routine Cleanup	Completed	9/3/1997	3/21/1998
Initial Investigation / Federal Preliminary Assessment	Completed		12/15/1997
LUST - Report Received	Completed		3/19/1998

# Cleanup Site Details

Cleanup Site ID: 6528

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		5/18/1998
LUST - Report Received	Completed		8/27/1998
LUST - Report Received	Completed		3/16/2001
LUST - Report Received	Completed		8/29/2003
LUST - Report Received	Completed		10/3/2003
LUST - Report Received	Completed		12/9/2004
VCP Opinion on Remedial Investigation Work Plan	Completed	12/18/2006	1/10/2007
Reopen Site	Completed		12/21/2006
Remedial Investigation and/or Feasibility Study	Completed	12/21/2006	1/10/2007
VCP Opinion on Remedial Investigation	Completed	4/6/2007	4/16/2007
LUST - Report Received	Completed		1/7/2009
LUST - Report Received	Completed		2/6/2009
VCP Opinion on Feasibility Study	Completed	2/25/2009	3/24/2009
VCP Opinion on Cleanup Action Plan	Completed	5/18/2009	6/18/2009
VCP Opinion on Cleanup Action	Canceled	10/15/2009	1/1/1900
Site Status Changed to NFA	Completed		12/17/2009
Periodic Review	Completed	5/1/2014	9/22/2014