

Cleanup Site Details

Cleanup Site ID: 6537

Cleanup Site ID: 6537 Facility/Site ID: 70996824 UST ID: 583072 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Chevron 209335 [Glossary](#)

Alternate Names: Chevron 209335, Seattle Housing Authority Maint Parking Lot, SEATTLE HOUSING AUTHORITY MAINT PKG LOT, SEATTLE HOUSING AUTHORITY MAINT PKG LOT CHEVRON

LOCATION

Address: 1201-1225 N 45TH ST **City:** SEATTLE **Zip Code:** 98103 **County:** King
Latitude: 47.66128 **Longitude:** -122.34297 **WRIA:** 8 **Legislative District:** 43 **Congressional District:** 7 **TRS:** 25N 4E 18

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Myers, Dale R **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 209335	Upland	Cleanup Started	NW	Myers, Dale R	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Lead		C				
Methyl tertiary-butyl ether	C					
Non-Halogenated Solvents	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/26/2001
LUST - Report Received	Completed		3/28/2001
LUST - Report Received	Completed		5/10/2001
LUST - Notification	Completed		7/19/2001

Cleanup Site Details

Cleanup Site ID: 6537

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		7/19/2001
LUST - Report Received	Completed		2/19/2002
LUST - Report Received	Completed		2/5/2003
LUST - Report Received	Completed		2/20/2004
LUST - Report Received	Completed		3/14/2005
Cleanup Action Plan	Completed	3/15/2005	6/15/2005
VCP Opinion on Interim Action	Canceled	3/15/2005	1/1/1900
VCP Status Request	Completed	5/4/2009	10/14/2009
LUST - Report Received	Completed		9/3/2009
VCP Opinion on Interim Action	Completed	11/20/2009	2/10/2010
Site Hazard Assessment	Completed	5/8/2017	2/1/2018
Hazardous Sites Listing	Completed		2/7/2018
LUST - Report Received	Completed		2/28/2018
Order/Decree/Amendment	In Process	2/21/2019	
LUST - Report Received	Completed		3/28/2019