

# Cleanup Site Details

Cleanup Site ID: 6537

Cleanup Site ID: 6537      Facility/Site ID: 70996824      UST ID: 583072      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Chevron 209335      [Glossary](#)

**Alternate Names:** Chevron 209335, Seattle Housing Authority Maint Parking Lot, SEATTLE HOUSING AUTHORITY MAINT PKG LOT, SEATTLE HOUSING AUTHORITY MAINT PKG LOT CHEVRON

## LOCATION

**Address:** 1201-1225 N 45TH ST      **City:** SEATTLE      **Zip Code:** 98103      **County:** King  
**Latitude:** 47.66128      **Longitude:** -122.34297      **WRIA:** 8      **Legislative District:** 43      **Congressional District:** 7      **TRS:** 25N 4E 18

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Myers, Dale R      **Responsible Unit:** Northwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 209335	Upland	Cleanup Started	NW	Myers, Dale R	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Lead		C				
Methyl tertiary-butyl ether	C					
Non-Halogenated Solvents	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/26/2001
LUST - Report Received	Completed		3/28/2001
LUST - Report Received	Completed		5/10/2001
LUST - Notification	Completed		7/19/2001

# Cleanup Site Details

Cleanup Site ID: 6537

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
LUST - Report Received	Completed		7/19/2001
LUST - Report Received	Completed		2/19/2002
LUST - Report Received	Completed		2/5/2003
LUST - Report Received	Completed		2/20/2004
LUST - Report Received	Completed		3/14/2005
Cleanup Action Plan	Completed	3/15/2005	6/15/2005
VCP Opinion on Interim Action	Canceled	3/15/2005	
VCP Status Request	Completed	5/4/2009	10/14/2009
LUST - Report Received	Completed		9/3/2009
VCP Opinion on Interim Action	Completed	11/20/2009	2/10/2010
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2017	2/1/2018
Hazardous Sites Listing/NPL	Completed		2/7/2018
LUST - Report Received	Completed		2/28/2018
Order/Decree/Amendment	In Process	2/21/2019	
LUST - Report Received	Completed		3/28/2019