

Cleanup Site Details

Cleanup Site ID: 663

Cleanup Site ID: 663	Facility/Site ID: 1399	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: German Car Service					Glossary	
Alternate Names: German Car Service						
LOCATION						
Address: 6215 MARTIN WAY E		City: OLYMPIA	Zip Code: 98516	County: Thurston		
Latitude: 47.05006	Longitude: -122.80023	WRIA: 13	Legislative District: 22	Congressional District: 10	TRS: 18N 1W 15	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 1/12/1996	Current VCP? No	Past VCP? No			
Site Rank: N/A	NFA Reason: Site Hazard Assessment	Brownfield? No				
Site Manager: Southwest Region	Responsible Unit: Southwest	Active Institutional Control?		No		
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
German Car Service	Upland	No Further Action Required	SW	Southwest Region	No Process	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	R					
Petroleum Products-Unspecified	R					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Status Changed to NFA	Completed			1/12/1996		
Site Hazard Assessment	Completed			1/12/1996		