

Cleanup Site Details

Cleanup Site ID: 6651

Cleanup Site ID: 6651 Facility/Site ID: 77133953 UST ID: 2200 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Sportland Mini Mart

[Glossary](#)

Alternate Names: SPORTLAND MINI MART

LOCATION

Address: 4400 BULLFROG RD City: CLE ELUM Zip Code: 98922 County: Kittitas
Latitude: 47.20761 Longitude: -120.98152 WRIA: 39 Legislative District: 13 Congressional District: 8 TRS: 20N 15E 21

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Lind, Jennifer Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Sportland Mini Mart	Upland	Cleanup Started	CE	Lind, Jennifer	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Non-Halogenated Solvents	C	C				
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		10/22/1998
Site Discovery/Release Report Received	Completed		10/28/1998
LUST - Report Received	Completed		10/28/1998
LUST - Site Characterization Report	Completed		11/23/1998
LUST - Report Received	Completed		12/30/1998
LUST - Report Received	Completed		1/29/2002
Early Notice Letter(s)	Completed		10/13/2010
Site Hazard Assessment/Federal Site Inspection	Completed	2/1/2011	6/28/2011

Cleanup Site Details

Cleanup Site ID: 6651

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	1/2/2012	1/20/2012
Hazardous Sites Listing/NPL	Completed		1/20/2012
VCP Receipt of Plan or Report	Completed		10/15/2012
VCP Opinion on Remedial Investigation	Completed	10/15/2012	10/17/2012
LUST - Report Received	Completed		1/31/2013
LUST - Report Received	Completed		7/13/2013
LUST - Report Received	Completed		7/18/2013
LUST - Report Received	Completed		7/17/2014
LUST - Report Received	Completed		7/17/2014
LUST - Report Received	Completed		7/17/2014
LUST - Report Received	Completed		7/17/2014
LUST - Report Received	Completed		2/19/2015
LUST - Report Received	Completed		2/19/2015
LUST - Report Received	Completed		3/17/2016
LUST - Report Received	Completed		3/17/2016
LUST - Report Received	Completed		3/17/2016
LUST - Report Received	Completed		3/17/2016
VCP Opinion on Remedial Investigation Work Plan	In Process	7/2/2024	