

Cleanup Site Details

Cleanup Site ID: 6762

Cleanup Site ID: 6762 Facility/Site ID: 84946863 UST ID: 97588 Site Page Site Documents View Map

Cleanup Site Name: Southgate Oil

Alternate Names: Muscatel Midway Property, SOUTHGATE OIL, Southgate Oil Sound Transit Parcels

LOCATION

Address: 23428 PACIFIC HWY S City: KENT Zip Code: 98032 County: King

Latitude: 47.39108 Longitude: -122.29454 WRIA: 9 Legislative District: 33 Congressional District: 9 TRS: 22N 4E 16

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 12/9/2024 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Song, Jing Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Southgate Oil Sound Transit Parcels	Upland	No Further Action Required	NW	Song, Jing	Standard Voluntary Cleanup
Muscatel Midway Properties	Upland	No Further Action Required	NW	Song, Jing	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
mstrument Type	Media	Restrictions/Requirements	Date	Number	County	I ax Faicei

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB					
Halogenated Solvents	RB					
Lead	RB					
Mercury	RB					
Metals - Other	RB					
Petroleum-Diesel	RB					
Petroleum-Gasoline	RB					
Petroleum-Other	RB					
Polycyclic Aromatic Hydrocarbons	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		5/15/2001

Toxics Cleanup Program Report Generated: 10/10/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
LUST - Report Received	Completed		5/15/2001		
Site Discovery/Release Report Received	Completed		5/15/2001		
LUST - Report Received	Completed		2/25/2002		
VCP Opinion on Cleanup Action	Completed	10/11/2002	6/9/2006		
VCP Receipt of Plan or Report	Completed		12/3/2020		
VCP Receipt of Plan or Report	Completed		12/3/2020		
VCP Receipt of Plan or Report	Completed		12/3/2020		
VCP Receipt of Plan or Report	Completed		12/3/2020		
VCP Receipt of Plan or Report	Completed		3/9/2021		
VCP Receipt of Plan or Report	Completed		3/9/2021		
VCP Opinion on Property Cleanup	Completed	3/9/2021	6/23/2021		
VCP Receipt of Plan or Report	Completed		5/19/2021		
LUST - Report Received	Completed		11/17/2021		
VCP Opinion on Property Cleanup	Completed	11/17/2021	6/15/2022		
LUST - Report Received	Completed		5/17/2022		
VCP Receipt of Plan or Report	Completed		10/30/2024		
VCP Opinion on Site Cleanup	Completed	10/30/2024	12/9/2024		
SHARP Assessment	Completed		11/20/2024		
Site Status Changed to NFA	Completed		12/9/2024		

Cleanup Site ID: 6762