

Cleanup Site Details

Cleanup Site ID: 6775

Cleanup Site ID: 6775	Facility/Site ID: 85894558	UST ID: 567586	Site Page	Site Documents	View Map
Cleanup Site Name: Bonjorni Site					Glossary
Alternate Names: BONJORNI SITE					

LOCATION

Address: 5281 VANTAGE HWY			City: ELLENSBURG	Zip Code: 98926	County: Kittitas
Latitude: 47.00043	Longitude: -120.46545	WRIA: 39	Legislative District: 13	Congressional District: 8	TRS: 18N 19E 33

DETAIL

Status: Cleanup Started	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bonjorni Site	Upland	Cleanup Started	CE	Central Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	C					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		11/22/2000
LUST - Notification	Completed		11/22/2000
LUST - Report Received	Completed		5/3/2001
LUST - Report Received	Completed		6/12/2014
LUST - Report Received	Completed		3/27/2015
LUST - Report Received	Completed		4/6/2015