

Cleanup Site Details

Cleanup Site ID: 6775

Cleanup Site ID: 6775 **Facility/Site ID:** 85894558 **UST ID:** 567586 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Bonjorni Site [Glossary](#)
Alternate Names: BONJORNI SITE

LOCATION

Address: 5281 VANTAGE HWY **City:** ELLENSBURG **Zip Code:** 98926 **County:** Kittitas
Latitude: 47.00043 **Longitude:** -120.46545 **WRIA:** 39 **Legislative District:** 13 **Congressional District:** 8 **TRS:** 18N 19E 33

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Central Region **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bonjorni Site	Upland	Cleanup Started	CE	Central Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/22/2000
LUST - Notification	Completed		11/22/2000
LUST - Report Received	Completed		5/3/2001
LUST - Report Received	Completed		6/12/2014
LUST - Report Received	Completed		3/27/2015
LUST - Report Received	Completed		4/6/2015