

Cleanup Site ID: 6814

Cleanup Site Details

Facility/Site ID: 88593256 UST ID: 618998 Site Page Site Documents View Map

Cleanup Site ID: 6814

Cleanup Site Name: Grand Building Valetor Cleaners

Glossary

Alternate Names: GRAND BUILDING Valetor Cleaners

LOCATION

Address: 3011 GRAND AVE City: EVERETT Zip Code: 98201 County: Snohomish

Latitude: 47.97739 Longitude: -122.21301 WRIA: 7 Legislative District: 38 Congressional District: 2 TRS: 29N 5E 30

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 5 - Lowest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Grand Building Valetor Cleaners	Unland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
	Media	Tree and the state of the state		Number	County	

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	С	S				
LUST - Other Hazardous Substance	С					
Non-Halogenated Solvents	С					
Petroleum Products-Unspecified		S				
Petroleum-Diesel	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/5/2004
LUST - Report Received	Completed		2/5/2004
Site Discovery/Release Report Received	Completed		2/5/2004
VCP Opinion on Cleanup Action	Completed	2/5/2004	3/22/2004
VCP Status Request	Completed	3/31/2006	6/16/2006
Site Hazard Assessment/Federal Site Inspection	Completed	4/9/2007	8/1/2007

Toxics Cleanup Program Report Generated: 5/1/2025 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 6814

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Hazardous Sites Listing/NPL	Completed		8/1/2007		
Initial Investigation / Federal Preliminary Assessment	Completed		6/3/2011		

Toxics Cleanup Program Report Generated: 5/1/2025 Page 2 of 2