

Cleanup Site Details

Cleanup Site ID: 6822

Cleanup Site ID: 6822 Facility/Site ID: 89172959 UST ID: 97251 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Dodge of Bellevue [Glossary](#)

Alternate Names: Dodge of Bellevue, PERFORMANCE DODGE

LOCATION

Address: 316 116TH AVE NE City: BELLEVUE Zip Code: 98004 County: King
Latitude: 47.61339 Longitude: -122.18469 WRIA: 8 Legislative District: 41 Congressional District: 9 TRS: 25N 5E 33

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 8/8/2018 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Maurer, Christopher Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Performance Dodge	Upland	No Further Action Required	NW	Maurer, Christopher	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Non-Halogenated Solvents	RB					
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB	RB				
Polychlorinated biPhenyls (PCB)	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/31/1989
LUST - Notification	Completed		4/1/1989
Site Discovery/Release Report Received	Completed		4/1/1989
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004

Cleanup Site Details

Cleanup Site ID: 6822

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
VCP Opinion on Cleanup Action	Completed	9/20/2004	11/15/2004
Site Status Changed to NFA	Completed		11/15/2004
LUST - Site Characterization Report	Completed		9/19/2016
Reopen Site	Completed		9/19/2016
VCP Opinion on Site Cleanup	Completed	9/19/2016	8/8/2018
VCP Receipt of Plan or Report	Completed		5/24/2017
Site Status Changed to NFA	Completed		8/8/2018