

Cleanup Site Details

Cleanup Site ID: 6822

Cleanup Site ID: 6822 Facility/Site ID: 89172959 UST ID: 97251 Site Page Site Documents View Map

Cleanup Site Name: Dodge of Bellevue

Alternate Names: Dodge of Bellevue, PERFORMANCE DODGE

LOCATION

Address: 316 116TH AVE NE City: BELLEVUE Zip Code: 98004 County: King

Latitude: 47.61339 Longitude: -122.18469 WRIA: 8 Legislative District: 41 Congressional District: 9 TRS: 25N 5E 33

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 8/8/2018 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Maurer, Christopher Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Performance Dodge
 Upland
 No Further Action Required
 NW
 Maurer, Christopher
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Non-Halogenated Solvents	RB							
Petroleum-Diesel	RB	RB						
Petroleum-Gasoline	RB	RB						
Polychlorinated biPhenyls (PCB)	RB							

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/31/1989
LUST - Notification	Completed		4/1/1989
Site Discovery/Release Report Received	Completed		4/1/1989
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004
LUST - Report Received	Completed		9/17/2004

Toxics Cleanup Program Report Generated: 10/20/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Report Received	Completed		9/17/2004			
LUST - Report Received	Completed		9/17/2004			
LUST - Report Received	Completed		9/17/2004			
LUST - Report Received	Completed		9/17/2004			
VCP Opinion on Cleanup Action	Completed	9/20/2004	11/15/2004			
Site Status Changed to NFA	Completed		11/15/2004			
LUST - Site Characterization Report	Completed		9/19/2016			
Reopen Site	Completed		9/19/2016			
VCP Opinion on Site Cleanup	Completed	9/19/2016	8/8/2018			
VCP Receipt of Plan or Report	Completed		5/24/2017			
Site Status Changed to NFA	Completed		8/8/2018			

Cleanup Site ID: 6822