

Cleanup Site Details

Cleanup Site ID: 6858

Cleanup Site ID: 6858 Facility/Site ID: 92132181 UST ID: 427942 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: SERVICE STATION 3733 S G ST [Glossary](#)

Alternate Names: SERVICE STATION, SERVICE STATION 3733 S G ST

LOCATION

Address: 3733 S G ST City: TACOMA Zip Code: 98408 County: Pierce
Latitude: 47.22320 Longitude: -122.43994 WRIA: 10 Legislative District: 27 Congressional District: 6 TRS: 20N 3E 16

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 5/9/2017 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Johnston, Carol Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WELLS FARGO BANK	Upland	No Further Action Required	SW	Johnston, Carol	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB					
Petroleum-Gasoline	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		7/25/1996
LUST - Report Received	Completed		11/15/1996
LUST - Report Received	Completed		2/20/2003
Site Discovery/Release Report Received	Completed		9/26/2006
VCP Opinion on Property Cleanup	Completed	1/9/2017	5/9/2017
Site Status Changed to NFA	Completed		5/9/2017
Petroleum Contaminated Soil Model Remedies	Completed		5/9/2017