

## Cleanup Site Details

Cleanup Site ID: 6858

Cleanup Site ID: 6858 Facility/Site ID: 92132181 UST ID: 427942 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: SERVICE STATION 3733 S G ST

Alternate Names: SERVICE STATION, SERVICE STATION 3733 S G ST

LOCATION

Address: 3733 S G ST City: TACOMA Zip Code: 98408 County: Pierce

Latitude: 47.22320 Longitude: -122.43994 WRIA: 10 Legislative District: 27 Congressional District: 6 TRS: 20N 3E 16

**DETAIL** 

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 5/9/2017 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Johnston, Carol Responsible Unit: Southwest Active Institutional Control? No

**CLEANUP UNITS** 

 
 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 WELLS FARGO BANK
 Upland
 No Further Action Required
 SW
 Johnston, Carol
 Standard Voluntary Cleanup

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB					
Petroleum-Gasoline	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
LUST - Notification	Completed		7/25/1996	
LUST - Report Received	Completed		11/15/1996	
LUST - Report Received	Completed		2/20/2003	
Site Discovery/Release Report Received	Completed		9/26/2006	
VCP Opinion on Property Cleanup	Completed	1/9/2017	5/9/2017	
Site Status Changed to NFA	Completed		5/9/2017	
Petroleum Contaminated Soil Model Remedies	Completed		5/9/2017	

Toxics Cleanup Program Report Generated: 6/30/2025 Page 1 of 1