

Cleanup Site Details

Cleanup Site ID: 6879

Cleanup Site ID: 6879	Facility/Site ID: 93219572	UST ID: 480423	Site Page	Site Documents	View Map
Cleanup Site Name: Bellis Fair Chevron					Glossary
Alternate Names: BELLIS FAIR CHEVRON					

LOCATION

Address: 1031 W BAKERVIEW RD			City: BELLINGHAM	Zip Code: 98226	County: Whatcom
Latitude: 48.78943	Longitude: -122.50716	WRIA: 1	Legislative District: 42	Congressional District: 2	TRS: 38N 2E 13

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 5/19/2006	Current VCP? No Past VCP? Yes
Site Rank: N/A	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No
Site Manager: Adams, Mark	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bellis Fair Chevron	Upland	No Further Action Required	NW	Adams, Mark	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Petroleum-Gasoline	C	C				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		11/4/2003
LUST - Report Received	Completed		11/4/2003
LUST - Report Received	Completed		3/29/2004
Cleanup Action Plan	Completed	3/31/2005	6/1/2005
VCP Opinion on Cleanup Action	Completed	3/31/2005	5/19/2006
LUST - Report Received	Completed		6/10/2005
Site Status Changed to NFA	Completed		5/19/2006