DEPARTMENT OF ECOLOGY State of Washington	Cl	eanup	Site D	)eta	ails		Cleanu	p Site ID: 689	
Cleanup Site ID: 689 Facility/Site ID: 807			ST ID: N/A		<u>Site P</u>	Site Page Site Docum		View Map	
Cleanup Site Name: Inland Power & Light Spill								<u>Glossary</u>	
Alternate Names: INLAND POWER	& LIGHT SPILL, In	and Power & Li	ght Transfor	mer Sp	bill				
LOCATION									
Address: HWY 195 & HWY 26 City: COLFAX					Zip Code:	99111	County: W	nitman	
Latitude: 46.89009 Longitude:	117.36519 <b>WRI</b>	<b>A</b> : 34 Leg	gislative Dis	strict:	9 Congres	sional Dis	strict: 5 T	<b>RS:</b> 16N 43E 11	
DETAIL									
Status: Awaiting Cleanup NFA Received? No					Is PSI site? No				
Statute: MTCA NFA Date: N/A				Current VCP? No Past VCP? No					
Site Rank: 3 - Moderate Risk NFA Reason: N/				Brownfield? No					
Site Manager: Eastern Region Responsible U			ern			itutional Con	trol? No		
CLEANUP UNITS									
Cleanup Unit Name	Unit Type	Unit Status		Resp Unit	Unit Manag	ger	Current Process		
Inland Power & Light Spill	Upland	Awaiting Cleanup		EA	Eastern Reg	jion	No Process		
ACTIVE INSTITUTIONAL CONTROL	S								
Instrument Type Restriction Media	Restrictio	Restrictions/Requirements				ording Imber	Recording County	Tax Parcel	
There are no current Institutional Controls in effect for this site.									
AFFECTED MEDIA & CONTAMINAN	TS								
					ME	DIA			
Contaminant	aminant Soil Ground		Groundw	ater	ater Surface Water		nent Air	Bedrock	
lychlorinated biPhenyls (PCB) C					S				
	onfirmed Above Cle emediated	anup Level	RA - Reme RB - Reme						
SITE ACTIVITIES									
Activity				Status		Start	Date C	End Date/ Completion Date	
Site Discovery/Release Report Received				Completed			6/15/1994		
Initial Investigation / Federal Preliminary Assessment				Completed			9/13/1994		
Early Notice Letter(s)				Completed			4/3/1995		
Site Hazard Assessment/Federal Site Inspection				Completed		8/25/1	/25/1998 12/28/1998		
Hazardous Sites Listing/NPL				Completed					