Cleanup Site ID: 6			Cleanup	o Site I	Deta	ails			Cleanup	o Sit	e ID: 6902
c.cump one iD. 0	902 Fa	cility/Site ID:	94125562	UST ID: 412	26		Site Page	<u>Site D</u>	ocuments		<u>View Map</u>
Cleanup Site Name	: Short Stop Fu	ıel									<u>Glossary</u>
Alternate Names: 1 CO JACKPOT FOO			0P #2, SHORT ST	OP 2, SHORT	T STOP	FUEL, TI	ME OIL CO) JACKPO	T FOOD N	/ART	, TIME OIL
Address: 1154 SW	/ BASIN			City: EPHRA	TA	Zip (Code: 988	23 C	ounty: Gr	ant	
Latitude: 47.30932	Longitude:	-119.55942	WRIA: 41	Legislative D	istrict:	13 C	ongressio	nal Distric	ct:4 T	RS:	
DETAIL											
Status: No Furth	er Action	NFA	Received? Y	es			ls P	SI site?	No		
Statute: MTCA	Date: 1	11/2/2007 Curre				ent VCP?	No F	Past	VCP? Yes		
Site Rank: N/A		NFA	Reason: V	oluntary Clea	nup Prog	gram Rev	iew Bro v	vnfield?	No		
Site Manager: Eas	tern Region	Resp	oonsible Unit: E	astern			Acti	ve Institut	ional Con	trol?	Yes
CLEANUP UNITS											
Cleanup U	nit Name	Unit Type	Unit Sta	atus	Resp Unit	Unit	Manager	ıger Cı		Current Process	
Jackpot Food Mart		Upland	No Further Action	on Required	EA	Easte	ern Region	Sta	Indard Vol	untar	y Cleanup
ACTIVE INSTITUTIO	ONAL CONTRO	LS									
Instrument Type	Restriction Media	Rest	rictions/Requirer	nents	6	ate	Record Numb		ecording County	·	Tax Parcel
Environmental Covenant	Soil	Prohibit Soil Di	Prohibit Soil Disturbance			10/12/2007 1224		83 Grant		0	0164-001; 14 168-000; 14- 169-000; 14- 0166-000
AFFECTED MEDIA	& CONTAMINA	INTS									
	& CONTAMINA	NTS	Soil	Groups	lwator	Surface	MEDIA		Air		Bodrock
AFFECTED MEDIA Contaminant Petroleum-Other	& CONTAMINA	NTS	Soil	Ground		Surface		Sediment	t Air		Bedrock
Contaminant	.evel C - (nediated	Above			: Air		Bedrock
Contaminant Petroleum-Other (ey: 3 - Below Cleanup L	.evel C - (Confirmed Abov	C	C RA - Rem	nediated	Above			t Air		Bedrock
Contaminant Petroleum-Other Key: 3 - Below Cleanup L S - Suspected	.evel C - (Confirmed Abov	C	C RA - Rem	nediated	Above				En	d Date/
Contaminant Petroleum-Other (ey: 3 - Below Cleanup L 5 - Suspected SITE ACTIVITIES Activity	.evel C - (Confirmed Abov	C	C RA - Rem	nediated-	Above Below	Water	Sediment		En Comp	d Date/
Contaminant Petroleum-Other A - Below Cleanup L B - Suspected SITE ACTIVITIES Activity	.evel C - (R - F	Confirmed Abov	C	C RA - Rem	nediated- nediated-	Above Below Status	e Water	Sediment		En Comp	d Date/ letion Date
Contaminant Petroleum-Other S - Below Cleanup L S - Suspected SITE ACTIVITIES Activity UST - Notification UST - Report Rece	.evel C - C R - F	Confirmed Abov	C	C RA - Rem	nediated nediated CC	Above Below Status	Water	Sediment		En Comp 11 7/	d Date/ letion Date /7/1990
Contaminant Petroleum-Other (ey: 3 - Below Cleanup L 5 - Suspected SITE ACTIVITIES Activity UST - Notification UST - Report Rece Site Characterization	evel C - (R - F	Confirmed Abov	C	C RA - Rem	nediated- nediated- CC	Above Below Status completed	Water Water Image: State	Sediment		En Comp 11 7/ 12	d Date/ letion Date /7/1990 15/1991
Contaminant Petroleum-Other (ey: 3 - Below Cleanup L 5 - Suspected SITE ACTIVITIES Activity UST - Notification UST - Report Rece Site Characterizatior UST - Report Rece	evel C - C R - F ived	Confirmed Abov	C	C RA - Rem	nediated nediated	Above Below Status completer completer	Water	Sediment		En Comp 11 7/ 12 6/	d Date/ letion Date /7/1990 15/1991 2/1/1992
Contaminant Petroleum-Other A - Below Cleanup L - Suspected SITE ACTIVITIES Activity UST - Notification UST - Report Rece Site Characterizatior UST - Report Rece	evel C - C R - F ived ived ived	Confirmed Abov	C	C RA - Rem	nediated nediated	Above Below Status completed completed	Water I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I I	Sediment		En Comp 11 7/ 12 6/ 12	d Date/ letion Date /7/1990 15/1991 2/1/1992 28/1993
Contaminant Petroleum-Other Key: 3 - Below Cleanup L 5 - Suspected SITE ACTIVITIES	evel C - C R - F	Confirmed Abov	C	C RA - Rem	nediated- nediated- c c c c c c c c c c c c c c c c c c c	Above Below Status completer completer completer	Water I I I <td>Sediment</td> <td></td> <td>En Comp 11 7/ 12 6/ 12 7,</td> <td>d Date/ letion Date /7/1990 15/1991 2/1/1992 28/1993 (10/1993</td>	Sediment		En Comp 11 7/ 12 6/ 12 7,	d Date/ letion Date /7/1990 15/1991 2/1/1992 28/1993 (10/1993
Contaminant Petroleum-Other (ey: 3 - Below Cleanup L S - Suspected SITE ACTIVITIES Activity UST - Notification LUST - Report Rece Site Characterizatior LUST - Report Rece LUST - Report Rece	evel C - C R - F	Confirmed Abov	C	C RA - Rem	nediated nediated CC CC CC CC CC CC CC CC CC	Above Below Status completer completer completer completer	Water I I I <td>Sediment</td> <td></td> <td>En comp 11 7/ 12 6/ 12 7. 5</td> <td>d Date/ letion Date /7/1990 15/1991 2/1/1992 28/1993 1/10/1993 1/1/1997</td>	Sediment		En comp 11 7/ 12 6/ 12 7. 5	d Date/ letion Date /7/1990 15/1991 2/1/1992 28/1993 1/10/1993 1/1/1997



Cleanup Site Details

SITE ACTIVITIES								
Activity	Status	Start Date	End Date/ Completion Date					
LUST - Report Received	Completed		3/6/2006					
VCP Opinion on Cleanup Action	Completed	3/6/2006	5/16/2007					
Site Status Changed to NFA	Completed		11/2/2007					
Periodic Review	Completed	2/13/2013	4/13/2013					
Periodic Review	Completed	2/13/2018	3/19/2018					
Periodic Review	Completed	2/1/2023	6/14/2023					