

Cleanup Site Details

Cleanup Site ID: 6910

Cleanup Site ID: 6910 Facility/Site ID: 94369212 UST ID: 956 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: DeBocks Main Street Texaco [Glossary](#)

Alternate Names: DEBOCKS MAIN STREET TEXACO

LOCATION

Address: 100 W WINE COUNTRY RD City: GRANDVIEW Zip Code: 98930 County: Yakima
Latitude: 46.25590 Longitude: -119.90212 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 9N 23E 23

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Wisotzkey, Chelsea Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
DeBocks Main Street Texaco	Upland	Cleanup Started	CE	Wisotzkey, Chelsea	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		5/4/1995
LUST - Notification	Completed		5/4/1995
LUST - Report Received	Completed		5/4/1995
LUST - Report Received	Completed		7/9/1998
LUST - Report Received	Completed		7/9/1998
LUST - Report Received	Completed		5/18/2006
LUST - Report Received	Completed		1/11/2019
LUST - Report Received	Completed		4/17/2019
LUST - Report Received	Completed		10/30/2019
VCP Opinion on Remedial Investigation	Completed	11/24/2020	1/20/2021

Cleanup Site Details

Cleanup Site ID: 6910

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Receipt of Plan or Report	Completed		12/4/2020
LUST - Report Received	Completed		12/4/2020
LUST - Report Received	Completed		2/5/2021
LUST - Report Received	Completed		12/16/2021
LUST - Report Received	Completed		2/19/2022
LUST - Report Received	Completed		12/30/2022
LUST Review Memo	Completed		11/15/2023
LUST - Report Received	Completed		5/21/2024
LUST - Report Received	Completed		6/3/2024
Order/Decree/Amendment	In Process	7/25/2024	