

Cleanup Site Details

Cleanup Site ID: 695

Cleanup Site ID: 695	Facility/Site ID: 2605	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Hansville Landfill					Glossary
Alternate Names: HANSVILLE LANDFILL					

LOCATION

Address: 7791 NE ECOLOGY RD			City: KINGSTON	Zip Code: 98346	County: Kitsap
Latitude: 47.84895	Longitude: -122.54906	WRIA: 15	Legislative District: 23	Congressional District: 6	TRS: 27N 2E 9

DETAIL

Status: Construction Complete- Performance Monitoring	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Nale, Cliff	Responsible Unit: Northwest	Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
HANSVILLE LANDFILL	Upland	Cleanup Started	NW	Nale, Cliff	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance, Prevent the Reuse or Relocation of Site Soil, Ongoing Maintenance of Remedy	8/22/2011	201108220304	Kitsap	092702-1-005-2007

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C	RB			
Metals Priority Pollutants		C	B			
Other Halogenated Organics		C	RB		RB	

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		12/3/1987
Site Hazard Assessment/Federal Site Inspection	Completed	5/1/1991	7/30/1991
Hazardous Sites Listing/NPL	Completed		8/30/1991
Order/Decree/Amendment	In Process	10/4/1995	
Remedial Investigation and/or Feasibility Study	Completed	1/1/1996	7/13/2007
Cleanup Action Plan	Completed		8/5/2011

Cleanup Site Details

Cleanup Site ID: 695

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Cleanup - Performance Monitoring	In Process	9/15/2011	
Periodic Review	Completed	9/26/2016	5/1/2017
Periodic Review	In Process	7/31/2023	