

Cleanup Site Details

Cleanup Site ID: 6974

Cleanup Site ID: 6974 Facility/Site ID: 97814788 UST ID: 1973 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Auto Warehousing Co Tacoma [Glossary](#)

Alternate Names: AUTO WAREHOUSING CO, AUTO WAREHOUSING CO TACOMA

LOCATION

Address: 3715 E WEST RD City: TACOMA Zip Code: 98421 County: Pierce
Latitude: 47.24769 Longitude: -122.37567 WRIA: 10 Legislative District: 27 Congressional District: 9 TRS: 20N 3E 1

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Malte, Dean Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
AUTO WAREHOUSING	Upland	Cleanup Started	SW	Malte, Dean	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Non-Halogenated Solvents	C	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/11/1990
LUST - Report Received	Completed		7/25/1990
LUST - Report Received	Completed		8/7/1990
LUST - Report Received	Completed		3/29/1991
LUST - Report Received	Completed		8/19/1991
LUST - Report Received	Completed		1/27/1992
LUST - Report Received	Completed		5/15/1992
LUST - Report Received	Completed		7/31/1992
LUST - Report Received	Completed		12/18/1992

Cleanup Site Details

Cleanup Site ID: 6974

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		3/21/1993
LUST - Site Assessment Report	Completed		1/5/2005
Site Discovery/Release Report Received	Completed		5/17/2006
Site Hazard Assessment/Federal Site Inspection	Completed	9/25/2007	2/6/2008
Hazardous Sites Listing/NPL	Completed		2/6/2008