

Cleanup Site Details

Cleanup Site ID: 7021

Cleanup Site ID: 7021 Facility/Site ID: 612 UST ID: 4947 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Moses Lake Port Pumphouse 1 [Glossary](#)

Alternate Names: MOSES LAKE PORT PUMPHOUSE 1, PORT OF MOSES LAKE, PORT OF MOSES LAKE DIESEL SPILL

LOCATION

Address: GRANT CNTY AIRPORT City: MOSES LAKE Zip Code: 98837 County: Grant
Latitude: 47.19321 Longitude: -119.31598 WRIA: 41 Legislative District: 13 Congressional District: 4 TRS: 20N 28E 28

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
Site Manager: Beck, Kristin Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port of Moses Lake/Pump House Area	Upland	Cleanup Started	EA	Beck, Kristin	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	B					
Petroleum-Diesel	B	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
30-Day Notice of PLP Status	Completed		
LUST - Notification	Completed		9/28/1992
Initial Investigation / Federal Preliminary Assessment	Completed		10/1/1992
Early Notice Letter(s)	Completed		10/30/1992
LUST - Report Received	Completed		1/11/1993
Site Hazard Assessment/Federal Site Inspection	Completed	2/18/1993	7/1/1993
LUST - Report Received	Completed		3/5/1993

Cleanup Site Details

Cleanup Site ID: 7021

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		8/17/1993
Hazardous Sites Listing/NPL	Completed		8/24/1993
LUST - Report Received	Completed		11/3/1995
LUST - Report Received	Completed		2/9/2009
LUST - Report Received	Completed		8/12/2009
LUST - Report Received	Completed		1/4/2010
LUST - Report Received	Completed		8/11/2010
Non-LUST Ind Report Received	Completed		1/5/2011
LUST - Report Received	Completed		1/5/2011
LUST - Report Received	Completed		9/12/2012
Order/Decree/Amendment	In Process	11/22/2022	
Remedial Investigation and/or FS Work Plan	In Process	12/26/2023	