

Cleanup Site Details

Cleanup Site ID: 7021

Cleanup Site ID: 7021 **Facility/Site ID:** 612 **UST ID:** 4947 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Moses Lake Port Pumphouse 1 [Glossary](#)
Alternate Names: MOSES LAKE PORT PUMPHOUSE 1, PORT OF MOSES LAKE, PORT OF MOSES LAKE DIESEL SPILL

LOCATION

Address: GRANT CNTY AIRPORT **City:** MOSES LAKE **Zip Code:** 98837 **County:** Grant
Latitude: 47.19321 **Longitude:** -119.31598 **WRIA:** 41 **Legislative District:** 13 **Congressional District:** 4 **TRS:** 20N 28E 28

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Beck, Kristin **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Port of Moses Lake/Pump House Area	Upland	Cleanup Started	EA	Beck, Kristin	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	B					
Petroleum-Diesel	B	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
30-Day Notice of PLP Status	Completed		
LUST - Notification	Completed		9/28/1992
Initial Investigation / Federal Preliminary Assessment	Completed		10/1/1992
Early Notice Letter(s)	Completed		10/30/1992
LUST - Report Received	Completed		1/11/1993
Site Hazard Assessment/Federal Site Inspection	Completed	2/18/1993	7/1/1993
LUST - Report Received	Completed		3/5/1993

Cleanup Site Details

Cleanup Site ID: 7021

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		8/17/1993
Hazardous Sites Listing/NPL	Completed		8/24/1993
LUST - Report Received	Completed		11/3/1995
LUST - Report Received	Completed		2/9/2009
LUST - Report Received	Completed		8/12/2009
LUST - Report Received	Completed		1/4/2010
LUST - Report Received	Completed		8/11/2010
Non-LUST Ind Report Received	Completed		1/5/2011
LUST - Report Received	Completed		1/5/2011
LUST - Report Received	Completed		9/12/2012
Order/Decree/Amendment	In Process	11/22/2022	
Remedial Investigation and/or FS Work Plan	In Process	12/26/2023	