

## Cleanup Site Details

Cleanup Site ID: 7021

Cleanup Site ID: 7021 Facility/Site ID: 612 UST ID: 4947 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: Moses Lake Port Pumphouse 1

Alternate Names: MOSES LAKE PORT PUMPHOUSE 1, PORT OF MOSES LAKE, PORT OF MOSES LAKE DIESEL SPILL

LOCATION

Address: GRANT CNTY AIRPORT City: MOSES LAKE Zip Code: 98837 County: Grant

Latitude: 47.19321 Longitude: -119.31598 WRIA: 41 Legislative District: 13 Congressional District: 4 TRS: 20N 28E 28

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Beck, Kristin Responsible Unit: Eastern Active Institutional Control? No

**CLEANUP UNITS** 

 
 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Port of Moses Lake/Pump House Area
 Upland
 Cleanup Started
 EA
 Beck, Kristin
 Independent Action

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

|                    | MEDIA |             |               |          |     |         |
|--------------------|-------|-------------|---------------|----------|-----|---------|
| Contaminant        | Soil  | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Lead               | В     |             |               |          |     |         |
| Petroleum-Diesel   | В     | С           |               |          |     |         |
| Petroleum-Gasoline | С     | С           |               |          |     |         |
| Petroleum-Other    | С     | С           |               |          |     |         |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

| Activity   | Status    | Start Date | End Date/<br>Completion Date |
|--|-----------|------------|------------------------------|
| LUST - Notification                                    | Completed |            | 9/28/1992                    |
| Initial Investigation / Federal Preliminary Assessment | Completed |            | 10/1/1992                    |
| Early Notice Letter(s)                                 | Completed |            | 10/30/1992                   |
| LUST - Report Received                                 | Completed |            | 1/11/1993                    |
| Site Hazard Assessment                                 | Completed | 2/18/1993  | 7/1/1993                     |
| LUST - Report Received                                 | Completed |            | 3/5/1993                     |
| LUST - Report Received                                 | Completed |            | 8/17/1993                    |

Toxics Cleanup Program Report Generated: 11/16/2025 Page 1 of 2



## Cleanup Site Details

| SITE ACTIVITIES                                 |            |                   |            |  |  |  |
|---|------------|-------------------|------------|--|--|--|
| Activity  | Status     | Status Start Date |            |  |  |  |
| Hazardous Sites Listing                         | Completed  |                   | 8/24/1993  |  |  |  |
| LUST - Report Received                          | Completed  |                   | 11/3/1995  |  |  |  |
| LUST - Report Received                          | Completed  |                   | 2/9/2009   |  |  |  |
| LUST - Report Received                          | Completed  |                   | 8/12/2009  |  |  |  |
| LUST - Report Received                          | Completed  |                   | 1/4/2010   |  |  |  |
| LUST - Report Received                          | Completed  |                   | 8/11/2010  |  |  |  |
| Non-LUST Ind Report Received                    | Completed  |                   | 1/5/2011   |  |  |  |
| LUST - Report Received                          | Completed  |                   | 1/5/2011   |  |  |  |
| LUST - Report Received                          | Completed  |                   | 9/12/2012  |  |  |  |
| 30-Day Notice of PLP Status                     | Completed  | 3/19/2019         | 4/19/2019  |  |  |  |
| Order/Decree/Amendment                          | In Process | 11/22/2022        |            |  |  |  |
| Remedial Investigation and/or FS Work Plan      | Completed  | 12/26/2023        | 11/22/2024 |  |  |  |
| SHARP Assessment                                | Completed  |                   | 6/5/2024   |  |  |  |
| Remedial Investigation and/or Feasibility Study | Planned    | 7/22/2026         | 1/1/1900   |  |  |  |

Cleanup Site ID: 7021