

## Cleanup Site Details

Cleanup Site ID: 7021

Cleanup Site ID: 7021 Facility/Site ID: 612 UST ID: 4947 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site Name: Moses Lake Port Pumphouse 1

Alternate Names: MOSES LAKE PORT PUMPHOUSE 1, PORT OF MOSES LAKE, PORT OF MOSES LAKE DIESEL SPILL

LOCATION

Address: GRANT CNTY AIRPORT City: MOSES LAKE Zip Code: 98837 County: Grant

Latitude: 47.19321 Longitude: -119.31598 WRIA: 41 Legislative District: 13 Congressional District: 4 TRS: 20N 28E 28

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Beck, Kristin Responsible Unit: Eastern Active Institutional Control? No

**CLEANUP UNITS** 

 
 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Port of Moses Lake/Pump House Area
 Upland
 Cleanup Started
 EA
 Beck, Kristin
 Independent Action

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	В					
Petroleum-Diesel	В	С				
Petroleum-Gasoline	С	С				
Petroleum-Other	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
30-Day Notice of PLP Status	Completed		
LUST - Notification	Completed		9/28/1992
Initial Investigation / Federal Preliminary Assessment	Completed		10/1/1992
Early Notice Letter(s)	Completed		10/30/1992
LUST - Report Received	Completed		1/11/1993
Site Hazard Assessment/Federal Site Inspection	Completed	2/18/1993	7/1/1993
LUST - Report Received	Completed		3/5/1993

Toxics Cleanup Program Report Generated: 1/2/2025 Page 1 of 2



## Cleanup Site Details

Cleanup Site ID: 7021

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Report Received	Completed		8/17/1993			
Hazardous Sites Listing/NPL	Completed		8/24/1993			
LUST - Report Received	Completed		11/3/1995			
LUST - Report Received	Completed		2/9/2009			
LUST - Report Received	Completed		8/12/2009			
LUST - Report Received	Completed		1/4/2010			
LUST - Report Received	Completed		8/11/2010			
Non-LUST Ind Report Received	Completed		1/5/2011			
LUST - Report Received	Completed		1/5/2011			
LUST - Report Received	Completed		9/12/2012			
Order/Decree/Amendment	In Process	11/22/2022				
Remedial Investigation and/or FS Work Plan	In Process	12/26/2023				

Toxics Cleanup Program Report Generated: 1/2/2025 Page 2 of 2