

### Cleanup Site Details

Cleanup Site ID: 7025

Cleanup Site ID: 7025 Facility/Site ID: 1166 UST ID: 10669 Site Page Site Documents View Map

Cleanup Site Name: Cowlitz Food & Fuel Glossary

Alternate Names: COWLITZ BP, COWLITZ FOOD & FUEL, Exit 59 Food & Fuel, Exit 59 Food & Fuel LLC

LOCATION

Address: 101 MULFORD RD City: TOLEDO Zip Code: 98591 County: Lewis

Latitude: 46.41879 Longitude: -122.88997 WRIA: 26 Legislative District: 20 Congressional District: 3 TRS: 11N 2W 23

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No

Site Manager: Teel, Steve Responsible Unit: Southwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ECOLOGY OVERSIGHT	Upland	Cleanup Started	SW	Teel, Steve	Ecology-supervised or conducted

#### **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

#### **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С				
Lead	С	С				
Petroleum-Diesel	С	С				
Petroleum-Gasoline	С	С				
Petroleum-Other	С	С				
Polycyclic Aromatic Hydrocarbons	С					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above

S - Suspected R - Remediated RB - Remediated-Below

#### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		3/13/1990
Site Discovery/Release Report Received	Completed		3/13/1990
LUST - Notification	Completed		4/2/1990
Order/Decree/Amendment	Canceled		4/11/1991
Remedial Investigation and/or Feasibility Study	Completed	1/1/1993	9/30/1993

Toxics Cleanup Program Report Generated: 5/10/2025 Page 1 of 3



# Cleanup Site Details

Cleanup Site ID: 7025

SITE ACTIVITIES				
Activity	Status	Start Date	End Date/ Completion Date	
Hazardous Sites Listing/NPL	Completed		9/7/1993	
Cleanup Action Plan	Completed	9/11/1993	2/1/1994	
LUST - Site Characterization Report	Completed		10/13/1993	
Order/Decree/Amendment	Canceled		5/15/1995	
Order/Decree/Amendment	Canceled		5/15/1995	
Order/Decree/Amendment	Canceled		5/15/1995	
LUST - Report Received	Completed		7/11/1995	
Order/Decree/Amendment	Canceled		10/13/1995	
LUST - Report Received	Completed		4/29/1998	
Cleanup - Construction	Completed	10/1/2000	3/15/2001	
Cleanup Action - Engineering Design	Completed	1/1/2001	3/1/2001	
O & M	Completed	3/1/2001	3/1/2010	
Order/Decree/Amendment	Canceled		4/7/2001	
Order/Decree/Amendment	Canceled		4/17/2001	
Order/Decree/Amendment	Canceled		4/17/2001	
LUST - Report Received	Completed		1/16/2003	
Remedial Investigation and/or Feasibility Study	Completed	4/1/2007	11/18/2021	
LUST - Report Received	Completed		11/1/2007	
LUST - Report Received	Completed		1/14/2009	
LUST - Report Received	Completed		1/14/2009	
Order/Decree/Amendment	In Process	12/21/2009		
LUST - Report Received	Completed		3/30/2010	
LUST - Report Received	Completed		4/23/2010	
LUST - Report Received	Completed		9/26/2010	
Interim Action - Construction	Completed	10/1/2010	5/18/2011	
LUST - Report Received	Completed		11/29/2010	
LUST - Report Received	Completed		12/23/2010	
LUST - Report Received	Completed		1/10/2011	
LUST - Report Received	Completed		2/9/2011	
LUST - Report Received	Completed		5/15/2011	
LUST - Report Received	Completed		5/16/2011	
Interim Action - Plan	Completed		5/18/2011	
Interim Action - Performance Monitoring	In Process	5/18/2011		
LUST - Report Received	Completed		6/2/2011	
LUST - Report Received	Completed		9/6/2011	
Toxics Cleanup Program Report Generated: 5/10/2025			Page 2 of 3	



## Cleanup Site Details

SITE ACTIVITIES				
Activity	Status	Start Date	End Date/ Completion Date	
LUST - Report Received	Completed		1/9/2012	
LUST - Report Received	Completed		3/5/2012	
LUST - Report Received	Completed		6/14/2012	
LUST - Report Received	Completed		9/24/2012	
LUST - Report Received	Completed		1/14/2013	
LUST - Report Received	Completed		1/28/2013	
LUST - Report Received	Completed		4/9/2013	
Remedial Investigation and/or FS Work Plan	Completed	7/30/2013	10/2/2013	
LUST - Report Received	Completed		8/9/2013	
LUST - Report Received	Completed		12/21/2018	
LUST - Report Received	Completed		2/20/2019	
LUST - Report Received	Completed		4/29/2019	
LUST - Report Received	Completed		7/11/2019	
LUST - Report Received	Completed		12/26/2019	
Cleanup Action Plan	Completed	12/17/2021	5/14/2024	
Order/Decree/Amendment	In Process	11/9/2023		
Cleanup Action - Engineering Design	In Process	5/29/2024		

Cleanup Site ID: 7025