

# Cleanup Site Details

Cleanup Site ID: 7025

Cleanup Site ID: 7025      Facility/Site ID: 1166      UST ID: 10669      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Cowlitz Food & Fuel      [Glossary](#)

Alternate Names: COWLITZ BP, COWLITZ FOOD & FUEL, Exit 59 Food & Fuel, Exit 59 Food & Fuel LLC

## LOCATION

Address: 101 MULFORD RD      City: TOLEDO      Zip Code: 98591      County: Lewis  
Latitude: 46.41879      Longitude: -122.88997      WRIA: 26      Legislative District: 20      Congressional District: 3      TRS: 11N 2W 23

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 2 - Moderate-High Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Teel, Steve      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ECOLOGY OVERSIGHT	Upland	Cleanup Started	SW	Teel, Steve	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Lead	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	C	C				
Polycyclic Aromatic Hydrocarbons	C					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		3/13/1990
Site Discovery/Release Report Received	Completed		3/13/1990
LUST - Notification	Completed		4/2/1990
Order/Decree/Amendment	Canceled		4/11/1991
Remedial Investigation and/or Feasibility Study	Completed	1/1/1993	9/30/1993

# Cleanup Site Details

Cleanup Site ID: 7025

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Hazardous Sites Listing	Completed		9/7/1993
Cleanup Action Plan	Completed	9/11/1993	2/1/1994
LUST - Site Characterization Report	Completed		10/13/1993
Order/Decree/Amendment	Canceled		5/15/1995
Order/Decree/Amendment	Canceled		5/15/1995
Order/Decree/Amendment	Canceled		5/15/1995
LUST - Report Received	Completed		7/11/1995
Order/Decree/Amendment	Canceled		10/13/1995
LUST - Report Received	Completed		4/29/1998
Cleanup - Construction	Completed	10/1/2000	3/15/2001
Cleanup Action - Engineering Design	Completed	1/1/2001	3/1/2001
O & M	Completed	3/1/2001	3/1/2010
Order/Decree/Amendment	Canceled		4/7/2001
Order/Decree/Amendment	Canceled		4/17/2001
Order/Decree/Amendment	Canceled		4/17/2001
LUST - Report Received	Completed		1/16/2003
Remedial Investigation and/or Feasibility Study	Completed	4/1/2007	11/18/2021
LUST - Report Received	Completed		11/1/2007
LUST - Report Received	Completed		1/14/2009
LUST - Report Received	Completed		1/14/2009
Order/Decree/Amendment	In Process	12/21/2009	
LUST - Report Received	Completed		3/30/2010
LUST - Report Received	Completed		4/23/2010
LUST - Report Received	Completed		9/26/2010
Interim Action - Construction	Completed	10/1/2010	5/18/2011
LUST - Report Received	Completed		11/29/2010
LUST - Report Received	Completed		12/23/2010
LUST - Report Received	Completed		1/10/2011
LUST - Report Received	Completed		2/9/2011
LUST - Report Received	Completed		5/15/2011
LUST - Report Received	Completed		5/16/2011
Interim Action - Plan	Completed		5/18/2011
Interim Action - Performance Monitoring	In Process	5/18/2011	
LUST - Report Received	Completed		6/2/2011
LUST - Report Received	Completed		9/6/2011

# Cleanup Site Details

Cleanup Site ID: 7025

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/9/2012
LUST - Report Received	Completed		3/5/2012
LUST - Report Received	Completed		6/14/2012
LUST - Report Received	Completed		9/24/2012
LUST - Report Received	Completed		1/14/2013
LUST - Report Received	Completed		1/28/2013
LUST - Report Received	Completed		4/9/2013
Remedial Investigation and/or FS Work Plan	Completed	7/30/2013	10/2/2013
LUST - Report Received	Completed		8/9/2013
LUST - Report Received	Completed		12/21/2018
LUST - Report Received	Completed		2/20/2019
LUST - Report Received	Completed		4/29/2019
LUST - Report Received	Completed		7/11/2019
LUST - Report Received	Completed		12/26/2019
Cleanup Action Plan	Completed	12/17/2021	5/14/2024
Order/Decree/Amendment	In Process	11/9/2023	
Cleanup Action - Engineering Design	Completed	5/29/2024	5/14/2025
Cleanup - Construction	Planned	9/15/2025	10/31/2025