

# Cleanup Site Details

Cleanup Site ID: 7027

Cleanup Site ID: 7027      Facility/Site ID: 2020      UST ID: 97414      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: King County Cedar Hills Landfill      [Glossary](#)

**Alternate Names:** Cedar Hills Landfill, Cedar Hills Ldfl Drum, Cedar Hills LUSTs, CEDAR HILLS REGIONAL LANDFILL, KING CNTY PUBLIC WORKS CEDAR HILLS, King Cnty Solid Wst Cedar Hills Landfill, King County Cedar Hills Landfill, KING COUNTY DEPT OF NATURAL RESOURCES SO, KING COUNTY DEPT OF NATURAL RESOURCES SOLID W, King County Dept of Natural Resources Solid Waste

## LOCATION

**Address:** 16645 228TH AVE SE      **City:** MAPLE VALLEY      **Zip Code:** 98038      **County:** King  
**Latitude:** 47.45688      **Longitude:** -122.04406      **WRIA:** 8      **Legislative District:** 5      **Congressional District:** 8      **TRS:** 23N 6E 28

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** WPCA - Ch. 90.48 RCW      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 5 - Lowest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** O'Connor, Tim      **Responsible Unit:** Solid Waste Program      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
King County Cedar Hills Landfill	Upland	Cleanup Started	SWP	Noell, Alan	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	C	C	S		C	
Conventional Contaminants, Inorganic	S	S	S		S	
Conventional Contaminants, Organic	S	S	S		S	
Halogenated Organics	C	C	S		S	
Metals - Other	S	C	S			
Metals Priority Pollutants		S				
Non-Halogenated Solvents	S	S	S		S	
Pesticides-Unspecified	S	S	S			
Petroleum Products-Unspecified		S	S			
Petroleum-Diesel	RB	B				
Phenolic Compounds	S	S	S			
Polychlorinated biPhenyls (PCB)	C		C			
Polycyclic Aromatic Hydrocarbons	S	C	C		S	

# Cleanup Site Details

Cleanup Site ID: 7027

**Key:**

B - Below Cleanup Level  
S - Suspected

C - Confirmed Above Cleanup Level  
R - Remediated

RA - Remediated-Above  
RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Hazardous Sites Listing/NPL	Completed		8/2/1992
Site Hazard Assessment/Federal Site Inspection	Completed		8/25/1992