

Cleanup Site Details

Cleanup Site ID: 7027

Cleanup Site ID: 7027 Facility/Site ID: 2020 UST ID: 97414 Site Page Site Documents View Map

Cleanup Site Name: King County Cedar Hills Landfill Glossary

Alternate Names: Cedar Hills Landfill, Cedar Hills Ldfl Drum, Cedar Hills LUSTs, CEDAR HILLS REGIONAL LANDFILL, KING CNTY PUBLIC WORKS CEDAR HILLS, King Cnty Solid Wst Cedar Hills Landfill, King County Cedar Hills Landfill, KING COUNTY DEPT OF NATURAL RESOURCES SO, KING COUNTY DEPT OF NATURAL RESOURCES SOLID W, King County Dept of Natural Resources Solid Waste

LOCATION

Address: 16645 228TH AVE SE City: MAPLE VALLEY Zip Code: 98038 County: King

Latitude: 47.45688 Longitude: -122.04406 WRIA: 8 Legislative District: 5 Congressional District: 8 TRS: 23N 6E 28

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: WPCA - Ch. 90.48 RCW NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 5 - Lowest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: O'Connor, Tim Responsible Unit: Solid Waste Program Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
King County Cedar Hills Landfill	Upland	Cleanup Started	SWP	Noell, Alan	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Base/Neutral/Acid Organics	С	С	S		С			
Conventional Contaminants, Inorganic	S	S	S		S			
Conventional Contaminants, Organic	S	S	S		S			
Halogenated Organics	С	С	S		S			
Metals - Other	S	С	S					
Metals Priority Pollutants		S						
Non-Halogenated Solvents	S	S	S		S			
Pesticides-Unspecified	S	S	S					
Petroleum Products-Unspecified		S	S					
Petroleum-Diesel	RB	В						
Phenolic Compounds	S	S	S					
Polychlorinated biPhenyls (PCB)	С		С					
Polycyclic Aromatic Hydrocarbons	S	С	С		S			

Toxics Cleanup Program Report Generated: 4/28/2024 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 7027

Key:B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
Site Discovery/Release Report Received	Completed		3/1/1988	
Hazardous Sites Listing/NPL	Completed		8/2/1992	
Site Hazard Assessment/Federal Site Inspection	Completed		8/25/1992	

Toxics Cleanup Program Report Generated: 4/28/2024 Page 2 of 2